Basic Vertebrate Fauna Survey and Risk Assessment

Menzies Mining Project

Prepared for: Kingwest Resources Ltd

Version 1. March, 2022





RECORD OF DISTRIBUTION

No. of copies	Report File Name	Report Status	Date	Prepared for:	Initials
Electronic	2021-0125-002-GT V1.DOCX	DRAFT	23 March 2022	Kingwest Resources Ltd	GT
Electronic	2021-0125-002-GT V1.DOCX	FINAL	23 March 2022	Kingwest Resources Ltd	ST

Suggested Citation: Terrestrial Ecosystems 2022 *Basic Vertebrate Fauna Survey and Risk Assessment for the Menzies Mining Project*, Unpublished report for Kingwest, Perth.

Prepared For: Kingwest Resources Ltd
Unit 3, Churchill Court
331-336 Hay Street
Subiaco WA 6008

Prepared By: Terrestrial Ecosystems
10 Houston Place
Mt Claremont WA 6010
Phone: 08 9385 2398, 0407 385 289
Website: www.terrestrialecosystems.com
ABN: 40921131346

DISCLAIMER
This document is prepared in accordance with and subject to an agreement between G & S Thompson Pty Ltd as Trustee for the Thompson Family Trust trading as Terrestrial Ecosystems and the client,Kingwest Resources Ltd. It has been prepared and is restricted to those issues that have been raised by the client in its engagement of Terrestrial Ecosystems and prepared using the standard of skill and care ordinarily exercised by environmental scientists in the preparation of such reports.

Persons or agencies that rely on or use this document for purposes or reasons other than those agreed by Terrestrial Ecosystems and its client without first obtaining prior consent, do so at their own risk and Terrestrial Ecosystems denies all liability in tort, contract or otherwise for any loss, damage or injury of any kind whatsoever (whether in negligence or otherwise) that may be suffered as a consequence.

REPORT CONTENTS

EXECUTIVE SUMMARY

1. INTRODUCTION 1

1.1 Background 1
1.2 Scope of works and project objectives 1

2. EXISTING ENVIRONMENT 2

2.1 Location of the project area 2
2.2 Land use history 2
2.3 Climate 2
2.4 Regional biological fauna context of project area 3
2.4.1 Fauna species at risk 3

3. METHODOLOGY 4

3.1 Database searches 4
3.2 Reconnaissance survey 4
3.3 Fauna habitat assessment 4
3.3.1 Survey and reporting staff 7
3.4 Limitations 7

4. RESULTS 9

4.1 Fauna habitat 9
4.1.1 Malleefowl 12
4.1.2 Feral fauna 12
4.1.3 Vertebrate fauna 13
4.1.4 Rubbish and deteriorating built infrastructure 13
4.1.5 Uncapped exploration drill holes 14
4.2 Bioregional vertebrate fauna 14
4.3 Conservation significant fauna 20
4.4 Risk assessment 25

5. DISCUSSION 28

5.1 Adequacy of the fauna survey data for fauna habitats represented in the project area 28
5.1.1 Amphibians 28
5.1.2 Reptiles 28
5.1.3 Birds 28
5.1.4 Mammals 29
5.2 Biodiversity value of the project area 29
5.2.1 Ecological functional value at the ecosystem level 29
5.2.2 Maintenance of threatened ecological communities 29
5.2.3 Condition of fauna habitat 29
5.2.4 Ecological linkages 29
5.2.5 Abundance and distribution of similar habitat in the adjacent areas 30

6. POTENTIAL IMPACTS 31

6.1 Potential impacts on fauna 31
6.2 Direct impacts 31
6.2.1 Animal deaths during the clearing process and displacement of fauna 31
6.2.2 Reduction or loss of activity areas and closure of burrows 31
6.3 Indirect impacts 31
6.3.1 Habitat fragmentation 32
6.3.2 Introduced fauna and weeds 32
6.3.3 Road fauna deaths 32
6.3.4 Fire 32
6.3.5 Anthropogenic activity 32
6.3.6 Dust 33
6.4 Native vegetation clearing principles 33
6.5 Referral under the EPBC Act 33
7. SUMMARY 34
8. MANAGEMENT STRATEGIES 35
8.1.1 Induction and awareness 35
8.1.2 Minimising secondary impacts to the habitat 35
8.1.3 Uncapped exploration drill holes 35
8.1.4 Feral pest species 35
9. REFERENCES 36

LIST OF CHARTS

Chart 1. Monthly weather averages for Menzies (Bureau of Meteorology 2022) 2

LIST OF PLATES

Plate 1. Bushy shrubland 10
Plate 2. Bushy shrubland 10
Plate 3. Casuarina woodland 10
Plate 4. Casuarina woodland 10
Plate 5. Eucalypt woodland 10
Plate 6. Eucalypt woodland 10
Plate 7. Open grassland 11
Plate 8. Open grassland 11
Plate 9. Shrubland on a ridge 11
Plate 10. Shrubland on a ridge 11
Plate 11. Shrubland 11
Plate 12. Shrubland 11
Plate 13. Previously disturbed area 12
Plate 14. Previously disturbed area 12
Plate 15. Rabbit scats 13
Plate 16. Dog tracks 13
Plate 17. Rubbish from past anthropogenic activity 13
Plate 18. Deteriorating machinery 13
Plate 19. Deteriorating machinery 14
Plate 20. Deteriorating machinery 14
Plate 21. Uncapped exploration drill hole 14
Plate 22. Uncapped exploration drill hole 14

LIST OF TABLES

Table 1. Fauna survey limitations and constraints 8
Table 2. Relationship between vegetation associations and fauna habitats 9
Table 3. Bird species recorded in areas adjacent to the project area 15
Table 4. Amphibian species recorded in areas adjacent to the project area 17
Table 5. Mammal species recorded in areas adjacent to the project area 17
Table 6. Reptile species recorded in areas adjacent to the project area 18
Table 7. Assessment of the potential impact on conservation significant fauna that could occur in the bioregion 21
Table 8. Fauna impact risk assessment descriptors 26
Table 9. Levels of acceptable risk 26
Table 10. A risk assessment of the impact of ground disturbance activity on fauna 27
Table 11. Assessment of impact on fauna and fauna assemblages using the native vegetation clearing principles 33

LIST OF FIGURES

Figure 1. Reginal location
Figure 2. Fauna habitat types and assessment locations

LIST OF APPENDICES

Appendix A. Results of the EPBC Act Protected Matters search
Appendix B. Vertebrate fauna recorded in biological surveys in the region
Appendix C. Definitions of significant fauna under the WA *Biodiversity Conservation Act 2016* and Priority Species
Appendix D. Rapid habitat assessment

EXECUTIVE SUMMARY

Kingwest Resources Ltd (i.e. Kingwest) is proposing to remine historical mines that are currently in care and maintenance. The project area consists of two parcels of land and included the Lady Harriet, Lady Shenton, First Hit, Yunndaga and Selkirk mines on tenements M29/0014, M29/0154, M29/0153, M29/0184 and M29/0088.

The Menzies Gold project area assessed was 1,565ha and is immediately west and south-west of the Menzies town site in the northern Goldfields. This Basic vertebrate fauna survey and risk assessment provides an indication of the vertebrate fauna species potentially in the project area and surrounds and indicates the potential impacts and consequences of mining the area.

There are seven broad fauna habitats in the entire project area:

- Bushy shrubland;
- Casuarina woodland;
- Eucalypt woodland;
- Open grassland;
- Shrubland on a ridge;
- Shrubland; and
- Previously disturbed areas.

Much of the project area is highly disturbed with multiple mining pits, waste dumps, vehicles tracks and built infrastructure. The density of the vegetation varies appreciably across the project area with many patches of bare ground.

The fauna habitats in the project area are similar to adjacent areas, with the consequence that a loss of habitat is unlikely to have a significant impact on the vertebrate fauna in a bioregional context.

The project area contains some low rocky ridges, but they are small and isolated, so it is unlikely that they support the Priority 4 Long-tailed Dunnart.

There is no requirement for an EPBC referral as the reopening and development of a mine will not significantly impact on conservation significant species.

It is recommended that:

- an induction program that includes a component on managing fauna is a mandatory component of working on the Menzies Gold project;
- pets are not permitted on site;
- all waste and rubbish be contained in bins and regularly removed from site or buried so it is unavailable to pest species;
- feeding of native fauna should be actively discouraged;
- a log of the location of all drill holes is maintained along with the person responsible for securely capping the hole; and
- feral pest management is included in the operational mine's fauna management plan for the project area.

1. INTRODUCTION

1.1 BACKGROUND

Kingwest Resources Ltd (i.e. Kingwest) is proposing to remine old mines that are currently in care and maintenance and immediately to the west and south-west of the Menzies town site (Figure 1). The project area consists of two parcels of land and included the Lady Harriet, Lady Shenton, First Hit, Yunndaga and Selkirk mines on tenements M29/0014, M29/0154, M29/0153, M29/0184 and M29/0088.

The project area assessed in this report comprised a total area of 1,565ha (Figure 2) and includes multiple pits, mine shafts, waste dumps and infrastructure developed during the previous mining activity.

Terrestrial Ecosystems was commissioned by Kingwest to undertake a Basic vertebrate fauna survey and risk assessment for the proposed Menzies gold project area. The purpose of this assessment was to provide information to the government environmental regulators on the potential impacts of vegetation clearing and mining activity on the vertebrate fauna assemblage to enable the proposed development to be adequately assessed. The methodology broadly follows that described in the Environmental Protection Authority (EPA; 2020) *Technical Guidance Terrestrial Fauna Surveys*.

1.2 SCOPE OF WORKS AND PROJECT OBJECTIVES

A Basic fauna survey and risk assessment involves undertaking a desktop review and site visit. The objectives of this fauna risk assessment were to:

- provide an indication of the vertebrate fauna assemblage (reptiles, amphibians, mammals and birds) on and near the project area so that potential impacts on the fauna and fauna assemblage might be adequately assessed;
- identify the presence and/or potential risk of impacts on species of conservation significance that are present or likely to be present in the project area;
- assess the impact and environmental risks associated with the proposed development on the fauna assemblage;
- determine if any additional surveys are required to assess the potential impact on fauna assemblages in the project area, in particular, impacts on species of conservation significance; and
- make recommendations that avoid, mitigate or minimise potential impacts on resident fauna.

To achieve these objectives, Terrestrial Ecosystems:

- searched the Department of Biodiversity, Conservation and Attractions' (DBCA) NatureMap database for threatened and priority species near the project area;
- searched the Commonwealth Governments database of fauna of national environmental significance to identify species potentially occurring within the area that are protected under the *Environment Protection and Biodiversity Conservation (EPBC) Act 1999* or international migratory bird agreements (JAMBA/CAMBA);
- reviewed Terrestrial Ecosystems' database (includes Atlas of Living Australia) to identify potential vertebrate fauna within the area;
- reviewed previous fauna surveys conducted near the project area;
- undertook a four day site investigation to identify available fauna habitat types and the possible presence of conservation significant species (e.g. Malleefowl);
- discussed the likelihood of species listed under the *EPBC Act 1999* and *Biodiversity Conservation Act 2016* being present in the project area; and
- provided management recommendations to avoid, mitigate and minimise potential impacts on the fauna in the project area.

2. EXISTING ENVIRONMENT

2.1 LOCATION OF THE PROJECT AREA

The project area is in the Murchison 1 (MUR1 – East Murchison subregion) IBRA bioregion. It includes the remains of an existing mining operation that are in care and maintenance, which included multiple pits and shafts, waste dumps, haul road and other tracks and built infrastructure.

Cowan (2003) described the East Murchison IBRA subregion as internally draining, with extensive areas of elevated red desert sandplains with minimal dune development. Broad plains with red-brown soils and breakaway complexes as well as red sandplains. Vegetation is dominated by Mulga woodlands often with ephemerals; hummock grasslands, saltbush shrublands and halosarcia shrublands.

Threatening process for conservation significant fauna were listed by Cowan (2003) as foxes and cats. In addition, cattle grazing and mining activity over many years have significantly degraded small parcels of land dotted throughout the landscape.

2.2 LAND USE HISTORY

The dominant land uses for the bioregion are native pasture to support grazing and unallocated crown land, and to a much lesser extent mining (Cowan 2003).

2.3 CLIMATE

The project area is characterised as semi-arid. Menzies, which is adjacent to the project area, has an annual rainfall of approximately 254mm, although this varies considerably from year-to-year. The highest mean maximum and minimum temperatures in Laverton are in January with an average of 35.1°C and 19.7°C, respectively (Bureau of Meteorology, 2022). The lowest mean daily maximum and minimum temperatures occur in July (Chart 1). Average monthly rainfall is heaviest in January - March.




Chart 1. Monthly weather averages for Menzies (Bureau of Meteorology 2022)

2.4 REGIONAL BIOLOGICAL FAUNA CONTEXT OF PROJECT AREA

Numerous vertebrate fauna surveys have been undertaken near the project area. These include:

- Bell, D.T., Bell, R.C. and Loneragan, W.A. (2007) Winter bird assemblages across an arid gradient in south-west Western Australia, *Journal of the Royal Society of Western Australia*, 90, 219-227.
- Cowan, M.A. and How, R.A. (2004) Comparisons of ground vertebrate assemblages in arid Western Australia in different seasons and decades, *Records of the Western Australian Museum*, 22, 91-100.
- Dell, J and How, R.A. (1988) Vertebrate fauna in The biological survey of the eastern goldfields of Western Australia Part 5: Edjudina - Menzies Study Area, *Records of the Western Australian Museum*, Supplement No. 31. pp 38-68.
- Ecologia Environment (2007) *Jump Up Dam Fauna Assessment*, Unpublished report for Heron Resources Limited, Perth.
- Hart and Associates, (2000) *Anaconda Nickel Ltd, Cawse Expansion Project, Fauna Survey*, Unpublished report for Anaconda Nickel Ltd, Perth.
- Keith Lindbeck and Associates (2012) *Central Yilgarn Iron Project (CYIP) Fauna Assessment*, Unpublished report for Jupiter Mines Ltd, Perth.
- Ninox Wildlife Consulting (1998) *A Vertebrate Fauna Survey of the Murrin Murrin Expansion Project*, Unpublished report for Anaconda Nickel Ltd, Perth.
- Thompson, S.A. (2004) *Mine site rehabilitation index using reptile assemblage as a bio-indicator*, PhD Thesis, Edith Cowan University, Perth plus additional data collected after the PhD project.

There are individual records for fauna contained in the Atlas of Living Australia which includes the Western Australian Museum collection and NatureMap's records that have also been accessed.

Fauna assessments of most value are the ones undertaken by Thompson, S.A. (2004) which include in excess of 120,000 trap nights of data in habitat similar to that in the project area, Cowan and How (2004), Dell and How (1988) and Ninox Wildlife Consulting (1998).

2.4.1 Fauna species at risk

Cowan (2003) reported the fauna species at risk in the East Murchison subregion as Bilby (*Macrotis lagotis*), Marsupial Mole (*Notoryctes typhlops*), Mulgara (*Dasycercus cristicauda*), Malleefowl (*Leipoa ocellata*), Princess Parrot (*Polytelis alexandrae*), Slender-billed Thornbill (*Acanthiza iredalei iredalei*), Giant Desert Skink (*Liopholis kintorei*) and Peregrine Falcon (*Falco peregrinus*). Since then, the Night Parrot and Arid Bronze Azure (butterfly) have been added to the list of species of conservation interest. This report assesses the potential for these species to be found in the project area and the potential impact that the proposed development might have on these species, and other conservation significant fauna.

3. METHODOLOGY

3.1 DATABASE SEARCHES

A search of the *EPBC Act 1999* online list of threatened species was undertaken to identify species of conservation interest to the Commonwealth Government under the *Environment Protection and Biodiversity Conservation Act (EPBC Act)*. The search area was square around the project area (Appendix A). In addition, a desktop search of the Terrestrial Ecosystems' fauna survey database was undertaken to develop an appreciation of the vertebrate fauna assemblages near the project area.

Other more general texts were also used to provide supplementary information on vertebrate fauna in the bioregion, including Tyler et al. (2000) for frogs; Storr et al. (1983, 1990, 1999, 2002) and Thompson and Thompson (2010) for reptiles; Johnstone and Storr (1998, 2004) for birds; and Van Dyck and Strahan (2008) for mammals.

Collectively these sources of information were used to create lists of species expected to utilise the project and adjacent areas. It should be noted that these lists will include species that have been recorded in the general region but are possibly vagrants and they will not generally be found in the project area due to a lack of suitable habitat. Vagrants can be recorded almost anywhere. Many of the bird, mammal, reptile and amphibian species have specific habitat requirements that may be present in the general area but not in the project area. Also, the ecology of many of these species is often not well understood and it can sometimes be difficult to indicate those species whose specific habitat requirements are not present in the project area. Consequently, many species will be included in the lists produced from database searches but will not be present in the actual project area.

There are errors in most databases, including NatureMap, Atlas of Living Australia and the WA Museum (WAM) collection. These errors occur because of a misidentification of individuals, taxonomic name changes and incorrect coordinates being entered into the database. Terrestrial Ecosystems was unable to verify the primary fauna records, so it has used the information provided. Readers should therefore appreciate that species lists and fauna surveys reported in the appendices may include these errors. These databases also contain historical records and therefore include species that are no longer present in the area (e.g. *Myrmecobius fasciatus*, *Bettongia lesueur* and *Macrotis lagotis*).

3.2 RECONNAISSANCE SURVEY

The project area was searched on foot and using an ATV for conservation significant fauna between 15 and 18 November 2021. The reconnaissance survey was also used to record fauna habitat types in the project area.

3.3 FAUNA HABITAT ASSESSMENT

The fauna habitat assessment was undertaken for the project area. This field assessment had two foci:

- assessing fauna habitat types and their condition; and
- assessing the possible presence of and recording evidence of conservation significant fauna so that mine planning can minimise impacts and so that mitigation and management strategies can be developed and implemented to reduce potential impacts.

The fauna habitat assessors stopped at multiple locations within the project area and recorded a suite of data about the fauna habitat and its condition. This information included a description of the habitat structure, habitat condition, landform, soils and vegetation and time since last fire (Table 1).

Table 1. Rapid habitat assessment checklist

Observer's Name:	
Coordinates of the location as UTM (GDA94):	
Fire history – options	
☐ > 5 years	
☐ 1-5 years	
☐ < 1 year	
Landform – options	
☐ Beach	☐ Lower slope
☐ Clay plain	☐ Mid slope
☐ Cliff	☐ Ridge
☐ Creek line	☐ River
☐ Dam	☐ Rocky outcrop / breakaway
☐ Drainage line	☐ Salt lake
☐ Dune crest	☐ Sand dune
☐ Dune slope	☐ Sand plain
☐ Dune swale	☐ Stony plain
☐ Escarpment	☐ Swamp
☐ Flat	☐ Undulating
☐ Gorge	☐ Upper slope
☐ Gully	☐ Wetland
☐ Intertidal / mangrove	☐ Water hole
☐ Lake / lake edge	
Habitat quality – options	
☐ *High quality fauna habitat* – These areas closely approximate the vegetation mix and quality that would have been in the area prior to any disturbance. The habitat has connectivity with other habitats and is likely to contain the most natural vertebrate fauna assemblage.	
☐ *Very good fauna habitat* - These areas show minimal signs of disturbance (e.g. grazing, clearing, fragmentation, weeds) and generally retain many of the characteristics of the habitat if it had not been disturbed. The habitat has connectivity with other habitats and fauna assemblages in these areas are likely to be minimally effected by disturbance.	
☐ *Good fauna habitat* – These areas showed signs of disturbance (e.g. grazing, clearing, fragmentation, weeds) but generally retain many of the characteristics of the habitat if it had not been disturbed. The habitat has connectivity with other habitats and fauna assemblages in these areas are likely to be affected by disturbance.	
☐ *Disturbed fauna habitat*– These areas showed signs of significant disturbance. Many of the trees, shrubs and undergrowth are cleared. These areas may be in the early succession and regeneration stages. Areas may show signs of significant grazing, containing weeds or have been damaged by vehicle or machinery. Habitats are fragmented or have limited connectivity with other fauna habitats. Fauna assemblages in these areas are likely to differ significantly from what might be expected in the area had the disturbance not occurred.	
☐ *Highly degraded fauna habitat* – These areas often have a significant loss of vegetation, an abundance of weeds, and a large number of vehicle tracks or are completely cleared. Limited or no fauna habitat connectivity. Fauna	

	assemblages in these areas are likely to be significantly different to what might have been in the area pre-disturbance.		
Habitat structure – combined into habitat description			
Upper stratum			
☐	Tall open woodland	☐	Scattered tall trees
☐	Tall woodland	☐	Scattered trees
☐	Open woodland	☐	Scattered low trees
☐	Woodland	☐	Low closed forest
☐	Open forest	☐	Low open forest
☐	Closed forest	☐	Low woodland
☐	Tall closed forest	☐	Low open woodland
☐	Tall open forest		
Middle stratum			
☐	Shrubland	☐	Open heath
☐	Tall shrubland	☐	Low closed heath
☐	Tall open shrubland	☐	Low open heath
☐	Low shrubland	☐	Tall closed scrub
☐	Scattered low shrubs	☐	Tall open scrub
☐	Low open shrubland	☐	Scattered tall shrubs
☐	Scattered tall shrubs	☐	Open shrubland
☐	Closed heath	☐	Scattered shrubs
Lower stratum			
☐	Closed hummock grassland	☐	Closed tussock grassland / sedgeland / herbland
☐	Mid-dense hummock grassland	☐	Tussock grass land / sedgeland / herbland
☐	Hummock grassland	☐	Open tussock grassland / sedgeland / herbland
☐	Open hummock grassland	☐	Scattered tussock / grasses / sedges / herbs
☐	Scattered hummock grassland	☐	Very open tussock grassland / herbland
Soil Type – options			
☐	Sand	☐	Silty loam
☐	Loamy sand	☐	Sand clay loam
☐	Clayey sand	☐	Clay
☐	Clay loam	☐	Peat / organic
☐	Silty clay loam	☐	Stony
☐	Sandy loam		
Soil colour - options			
☐	Black	☐	Red
☐	Brown	☐	White

☐	Grey	☐	Yellow
☐	Orange		
Surface stones – options			
☐	None	☐	Boulders (>250mm)
☐	Pebbles (0-50mm)	☐	Rocks
☐	Cobbles (51-250)		

3.3.1 Survey and reporting staff

Drs Scott and Graham Thompson undertook the site investigation and fauna habitat assessment between 15-18 November 2021. Dr Graham Thompson prepared the report and Dr Scott Thompson reviewed the report before it was sent to the client. Both senior scientists have appropriate relevant post-graduate qualifications, extensive experience in conducting fauna assessments in the Goldfields, have published research articles on biodiversity, fauna assemblages, conservation significant species, trapping techniques and temporal variations in trapped fauna assemblages based on Goldfields surveys and are therefore appropriately trained and experienced for the task of preparing this assessment.

3.4 LIMITATIONS

This Basic vertebrate fauna survey and risk assessment is based on information contained in the Commonwealth Government online EPBC matters of national environmental significance (MNES) database and other published and unpublished fauna survey data for the bioregion and a site visit. It is acknowledged that multiple surveys conducted in different seasons, repeated over several years are necessary to fully appreciate the fauna assemblage in the project area.

The EPA's (2020) *Technical Guidance - Terrestrial vertebrate fauna surveys for environmental impact assessment* suggested that fauna surveys may be limited by many variables. Limitations associated with each of these variables are assessed in Table 2.

Table 2. Fauna survey limitations and constraints

Possible limitations	Constraint (yes/no); significant, moderate or negligible	Comment
Availability of data and information	Yes, negligible	There are vertebrate fauna survey data available for similar habitats near the project area.
Competency/experience of the survey team, including experience in the bioregion surveyed	No	The authors of this report have appropriate post-graduate qualifications, undertaken multiple surveys and assessments in the Goldfields, have published a book and multiple refereed journal articles based on fauna surveys in the region and are familiar with the vertebrate fauna in this bioregion.
Scope of the survey, e.g. where faunal groups were excluded from the survey	N/A	
Timing, weather and season	No	Weather was suitable for a site visit.
Disturbance that may have affected results, e.g. fire, flood	No	Disturbances in the project area have been factored into this assessment.
The proportion of fauna identified, recorded or collected	N/A	
Adequacy of the survey intensity and proportion of survey achieved, e.g. the extent to which the area was surveyed	No	Discussed in the report.
Access problems	No	There were no access problems.
Problems with data and analysis, including sampling biases	N/A	

N/A = not applicable, Significant = major impact on outcome of the assessment, Moderate = impacted parts of the assessment, Negligible = almost no impact on the assessment.

4. RESULTS

4.1 FAUNA HABITAT

There are seven broad fauna habitats in the project area, and these are based on the vegetation communities prepared by Western Botanical (2021):

- Bushy shrubland;
- Casuarina woodland;
- Eucalypt woodland;
- Open grassland;
- Shrubland on a ridge;
- Shrubland; and
- Previously disturbed areas.

Table 3. Relationship between vegetation associations and fauna habitats

Veg code	Vegetation association	Description	Fauna habitats
LIRS	Lateritic ironstone ridge *Acacia* shrublands	Lateritic ironstone ridges with mixed *Acacia* shrublands.	Shrubland on ridge
CpAsS	Casuarina pauper - *Acacia sibirica* shrublands	Stoney rises and plains with moderate to abundant mixed mantles of greenstone, quartz and ironstone pebbles cobbles, supporting prominent *Casuarina pauper* overstoreys with *Acacia sibirica*.	Casuarina woodland
CPBS	Calcyphytic pearl bluebush (*Maireana sedifolia*) shrublands	Stoney plains and slopes of greenstone hills supporting *Maireana sedifolia.*	Bushy shrubland
EsSafS	*Eremophila scoparia* - *Senna artemisioides* subsp. Filifolia shrublands	Alluvial plains with sparse overstories and dominant *Eremophila scoparia* and *Senna artemisioides* midstoreys.	Bushy shrubland
PSAS	Sago bush (*Maireana pyramidata*) low shrubland	Alluvial plains with red earths or duplex soils on hardpan dominated by *Maireana pyramidata*.	Bushy shrubland
EclW	Calcrete platform *Eucalyptus cleandiorum* woodlands	Low precipitated calcrete platforms supporting dominant *Eucalyptus clelandiorum* overstoreys with chenopod low shrublands.	Eucalpyt woodland
EolW	Calcareous plain *Eucalyptus oleosa* - *Acacia* woodlands	Very gently undulating to level plains with dominant *Eucalyptus oleosa* overstory, and *Acacia aneura, Eremophila oppositifolia, Eremophila scoparia* midstory.	Eucalpyt woodland
EcoW	Calcareous plain *Eucalyptus concinna* - *Acacia* woodlands	Very gently undulating to level plains with dominant *Eucalyptus concinna* overstory, and *Acacia aneura, Eremophila oppositifolia, Eremophila scoparia* midstory.	Eucalypt woodland
OG	Open grassland	Alluvial plains dominated grasses and low chenopods.	Open grassland
DRMS	Drainage tract Mulga shrublands	Narrow unincised linear drainage zones receiving concentrated run-on, supporting *A. aneura* tall shrublands.	Shrubland
GHAS-As	Greenstone hill *Acacia sibirica* shrublands	Hills and low rises of red earths on greenstone or basalt indurated by iron, supporting *Acacia sibirica.*	Shrubland
GHAS-Ac	Greenstone hill *Acacia collegialis* shrublands	Summits of greenstone and basalt hills dominated by *Acacia collegialis.*	Shrubland
EceW	Greenstone hill *Eucalyptus celastroides* woodlands	Eroding greenstone or basalt hill slopes supporting dominant *Eucalyptus celastroides* overstoreys with poorly developed mid and sub-strata.	Eucalypt woodland
HPMS	Hardpan mulga shrublands	Level to very gentle inclined plains subject to sheet flow, often with mantles of fine ironstone gravel, supporting scattered to moderately close *Acacia aneura* tall shrublands.	Shrubland
	Disturbed		Previously disturbed

Images of each of the fauna habitat types as shown in Plates 1-14.



Plate 1. Bushy shrubland



Plate 2. Bushy shrubland



Plate 3. Casuarina woodland



Plate 4. Casuarina woodland



Plate 5. Eucalypt woodland



Plate 6. Eucalypt woodland



Plate 7. Open grassland



Plate 8. Open grassland



Plate 9. Shrubland on a ridge



Plate 10. Shrubland on a ridge



Plate 11. Shrubland



Plate 12. Shrubland



Plate 13. Previously disturbed area



Plate 14. Previously disturbed area

The results of the rapid habitat assessment are provided in Appendix D. Images of the habitat at each of these assessment points provides a more comprehensive overview of the habitats in the project area and along the infrastructure corridor.

4.1.1 Malleefowl

The project area was searched for Malleefowl mounds and tracks. Malleefowl are predominantly a ground dwelling species and walk a considerable distance each day foraging for insects and seeds. Their tracks are distinctive, and in areas of soft sand or on sand tracks their presence is easily detected. No Malleefowl mounds or tracks were observed during the site visit, and there was little habitat in the project area suitable for Malleefowl.

Given anthropogenic disturbance in the project area over a period of many years, it was not anticipated that Malleefowl would be recorded in the project area.

4.1.2 Feral fauna

Rabbit scats (Plate 15) and dog prints (Plate 16) were recorded at multiple locations in the project area. A domestic/stray dog was recorded in the project area, so it is unknown whether the dog prints are from domestic/stray dogs wandering in the area or wild dogs.




Plate 15. Rabbit scats



Plate 16. Dog tracks

4.1.3 Vertebrate fauna

Very little native vertebrate fauna were observed in the project area during the site assessment, suggesting that anthropogenic activity over an extended period has appreciably reduced their abundance.

4.1.4 Rubbish and deteriorating built infrastructure

There was an abundance of rubbish spread across the many sections of the project area, but mostly in the north and around old mine sites and a substantial quantity of deteriorating built infrastructure and machinery around the mining pits.



Plate 17. Rubbish from past anthropogenic activity



Plate 18. Deteriorating machinery



Plate 19. Deteriorating machinery



Plate 20. Deteriorating machinery



Plate 21. Uncapped exploration drill hole



Plate 22. Uncapped exploration drill hole

4.1.5 Uncapped exploration drill holes

There was evidence of uncapped drill holes at multiple locations. Uncapped drill holes with the opening at ground level are a pit-trap for small vertebrates, from which they cannot escape (Malnic 1997). It is important that when exploration activity associated with a drill hole has been concluded, the holes are appropriately capped. Typically, this is best achieved by maintaining a record of where drill holes are, and who was responsible for securely capping them.

4.2 BIOREGIONAL VERTEBRATE FAUNA

Appendix B provides a summary of the fauna survey data that are available near the project area. There are appreciable differences in the recorded fauna assemblages within and among fauna surveys shown in Appendix B. These differences are partially due to the low survey effort often deployed and they also reflect variations in soils and vegetation as well as temporal variations in the fauna assemblages.

Tables 4-7 provide a list of vertebrate species potentially found near the project area that have been compiled based on the fauna survey report results shown in Appendix B.

Table 4. Bird species recorded in areas adjacent to the project area

Family	Species	Common Name
Casuariidae	*Dromaius novaehollandiae*	Emu
Megapodiidae	*Leipoa ocellata*	Malleefowl
Phasianidae	*Coturnix pectoralis*	Stubble Quail
Anatidae	*Biziura lobata*	Musk Duck
	Stictonetta naevosa	Freckled Duck
	Cygnus atratus	Black Swan
	Tadorna tadornoides	Australian Shelduck
	Chenonetta jubata	Australian Wood Duck
	Malacorhynchus membranaceus	Pink-eared Duck
	Anas gracilis	Grey Teal
	Anas superciliosa	Pacific Black Duck
	Aythya australis	Hardhead
Podicipedidae	*Poliocephalus poliocephalus*	Hoary-headed Grebe
Columbidae	*Phaps chalcoptera*	Common Bronzewing
	Ocyphaps lophotes	Crested Pigeon
	Geopelia cuneata	Diamond Dove
Podargidae	*Podargus strigoides*	Tawny Frogmouth
Caprimulgidae	*Eurostopodus argus*	Spotted Nightjar
Aegothelidae	*Aegotheles cristatus*	Australian Owlet-nightjar
Apodidae	*Apus pacificus*	Fork-tailed Swift
Otididae	*Ardeotis australis*	Australian Bustard
Anhingidae	*Anhinga melanogaster*	Australasian Darter
Ardeidae	*Ardea pacifica*	White-necked Heron
	Egretta novaehollandiae	White-faced Heron
	Ardea alba	Great Egret
Threskiornithidae	*Platalea flavipes*	Yellow-billed Spoonbill
Accipitridae	*Elanus axillaris*	Black-shouldered Kite
	Lophoictinia isura	Square-tailed Kite
	Haliaeetus albicilla	White-bellied Sea-eagle
	Haliastur sphenurus	Whistling Kite
	Accipiter fasciatus	Brown Goshawk
	Accipiter cirrocephalus	Collared Sparrowhawk
	Circus assimilis	Spotted Harrier
	Aquila audax	Wedge-tailed Eagle
	Hieraaetus morphnoides	Little Eagle
Falconidae	*Falco cenchroides*	Nankeen Kestrel
	Falco berigora	Brown Falcon
	Falco longipennis	Australian Hobby
	Falco peregrinus	Peregrine Falcon
Rallidae	*Tribonyx ventralis*	Black-tailed Native-hen
	Fulica atra	Eurasian Coot
Recurvirostridae	*Himantopus himantopus*	Black-winged Stilt
	Recurvirostra novaehollandiae	Red-necked Avocet
	Cladorhynchus leucocephalus	Banded Stilt
Charadriidae	*Charadrius ruficapillus*	Red-capped Plover
	Elseyornis melanops	Black-fronted Dotterel
	Erythrogonys cinctus	Red-kneed Dotterel
	Vanellus tricolor	Banded Lapwing
Scolopacidae	*Tringa nebularia*	Common Greenshank
Turnicidae	*Turnix velox*	Little Button-quail
Laridae	*Chlidonias hybridus*	Whiskered Tern
	Chroicocephalus novaehollandiae	Silver Gull
Cacatuidae	*Eolophus roseicapillus*	Galah
	Nymphicus hollandicus	Cockatiel
Psittacidae	*Glossopsitta porphyrocephala*	Purple-crowned Lorikeet
	Polytelis anthopeplus	Regent Parrot
	Platycercus icterotis	Western Rosella
	Barnardius zonarius	Australian Ringneck
	Psephotus varius	Mulga Parrot
	Melopsittacus undulatus	Budgerigar
	Neopsephotus bourkii	Bourke's Parrot

Family	Species	Common Name
	Neophema splendida	Scarlet-chested Parrot
Cuculidae	*Chalcites basalis*	Horsfield's Bronze-cuckoo
	Chalcites osculans	Black-eared Cuckoo
	Cacomantis pallidus	Pallid Cuckoo
Strigidae	*Ninox novaeseelandiae*	Southern Boobook
Halcyonidae	*Dacelo novaeguineae*	Laughing Kookaburra
	Todiramphus pyrrhopygius	Red-backed Kingfisher
Meropidae	*Merops ornatus*	Rainbow Bee-eater
Climacteridae	*Climacteris affinis*	White-browed Treecreeper
	Climacteris rufa	Rufous Treecreeper
Ptilonorhynchidae	*Ptilonorhynchus maculatus*	Spotted Bowerbird
	Ptilonorhynchus guttatus	Western Bowerbird
Maluridae	*Malurus splendens*	Splendid Fairy-wren
	Malurus leucopterus	White-winged Fairy-wren
	Malurus lamberti	Variegated Fairy-wren
	Malurus pulcherrimus	Blue-breasted Fairy-wren
Acanthizidae	*Pyrrholaemus brunneus*	Redthroat
	Smicrornis brevirostris	Weebill
	Gerygone fusca	Western Gerygone
	Acanthiza robustirostris	Slaty-backed Thornbill
	Acanthiza chrysorrhoa	Yellow-rumped Thornbill
	Acanthiza uropygialis	Chestnut-rumped Thornbill
	Acanthiza iredalei	Slender-billed Thornbill
	Acanthiza apicalis	Inland Thornbill
	Aphelocephala leucopsis	Southern Whiteface
Pardalotidae	*Pardalotus punctatus*	Spotted Pardalote
	Pardalotus rubricatus	Red-browed Pardalote
	Pardalotus striatus	Striated Pardalote
Meliphagidae	*Certhionyx variegatus*	Pied Honeyeater
	Lichenostomus virescens	Singing Honeyeater
	Lichenostomus leucotis	White-eared Honeyeater
	Lichenostomus ornatus	Yellow-plumed Honeyeater
	Lichenostomus plumulus	Grey-fronted Honeyeater

Family	Species	Common Name
	Lichenostomus penicillatus	White-plumed Honeyeater
	Purnella albifrons	White-fronted Honeyeater
	Manorina flavigula	Yellow-throated Miner
	Acanthagenys rufogularis	Spiny-cheeked Honeyeater
	Anthochaera carunculata	Red Wattlebird
	Conopophila whitei	Grey Honeyeater
	Epthianura tricolor	Crimson Chat
	Epthianura albifrons	White-fronted Chat
	Sugomel niger	Black Honeyeater
	Lichmera indistincta	Brown Honeyeater
	Phylidonyris niger	White-cheeked Honeyeater
	Melithreptus brevirostris	Brown-headed Honeyeater
Pomatostomidae	*Pomatostomus superciliosus*	White-browed Babbler
Psophodidae	*Cinclosoma castanotum*	Chestnut Quail-thrush
	Cinclosoma castaneothorax	Chestnut-breasted Quail-thrush
	Psophodes occidentalis	Chiming Wedgebill
Neosittidae	*Daphoenositta chrysoptera*	Varied Sittella
Campephagidae	*Coracina maxima*	Ground Cuckoo-shrike
	Coracina novaehollandiae	Black-faced Cuckoo-shrike
	Lalage sueurii	White-winged Triller
Pachycephalidae	*Pachycephala inornata*	Gilbert's Whistler
	Pachycephala pectoralis	Golden Whistler
	Pachycephala rufiventris	Rufous Whistler
	Colluricincla harmonica	Grey Shrike-thrush
	Oreoica gutturalis	Crested Bellbird
Artamidae	*Artamus personatus*	Masked Woodswallow
	Artamus superciliosus	White-browed Woodswallow
	Artamus cinereus	Black-faced Woodswallow
	Artamus cyanopterus	Dusky Woodswallow
	Artamus minor	Little Woodswallow
	Cracticus torquatus	Grey Butcherbird
	Cracticus nigrogularis	Pied Butcherbird

Family	Species	Common Name
	Cracticus tibicen	Australian Magpie
	Strepera versicolor	Grey Currawong
Rhipiduridae	*Rhipidura albiscapa*	Grey Fantail
	Rhipidura leucophrys	Willie Wagtail
Corvidae	*Corvus coronoides*	Australian Raven
	Corvus bennetti	Little Crow
	Corvus orru	Torresian Crow
Monarchidae	*Grallina cyanoleuca*	Magpie-lark
Petroicidae	*Microeca fascinans*	Jacky Winter
	Petroica goodenovii	Red-capped Robin
	Melanodryas cucullata	Hooded Robin
	Drymodes brunneopygia	Southern Scrub-robin

Family	Species	Common Name
Megaluridae	*Cincloramphus mathewsi*	Rufous Songlark
	Cincloramphus cruralis	Brown Songlark
Timaliidae	*Zosterops lateralis*	Silvereye
Hirundinidae	*Cheramoeca leucosterna*	White-backed Swallow
	Hirundo rustica	Barn Swallow
	Hirundo neoxena	Welcome Swallow
	Petrochelidon ariel	Fairy Martin
	Hirundo nigricans	Tree Martin
Nectariniidae	*Dicaeum hirundinaceum*	Mistletoebird
Estrildidae	*Taeniopygia guttata*	Zebra Finch
Motacillidae	*Anthus novaeseelandiae*	Australasian Pipit

Table 5. Amphibian species recorded in areas adjacent to the project area

Family	Species	Common Name
Hylidae	*Cyclorana maini*	Sheep Frog
	Cyclorana platycephala	Water-holding Frog
	Litoria cyclorhyncha	Spotted-thighed Frog
	Litoria moorei	Motorbike Frog
Limnodynastidae	*Neobatrachus kunapalari*	Kunapalari Frog
	Neobatrachus sudelli	Sudell's Frog

Family	Species	Common Name
	Neobatrachus sutor	Shoemaker Frog
	Neobatrachus wilsmorei	Goldfields Bullfrog
	Platyplectrum spenceri	Spencer's Burrowing Frog
Myobatrachidae	*Crinia georgiana*	Quacking Frog
	Pseudophryne occidentalis	Orange-crowned Toadlet

Table 6. Mammal species recorded in areas adjacent to the project area

Family	Species	Common Name
Bovidae	*Bos taurus*	Cow
	Capra hircus	Goat
	Ovis aries	Sheep
Camelidae	*Camelus dromedarius*	Dromedary
Suidae	*Sus scrofa*	Pig
Canidae	*Canis familiaris*	Dog
	Canis lupus	Dingo
	Vulpes vulpes	Red Fox
Felidae	*Felis catus*	House Cat
Emballonuridae	*Taphozous hilli*	Hill's Sheath-tail Bat

Family	Species	Common Name
Molossidae	*Austronomus australis*	White-striped Free-tail Bat
	Mormopterus planiceps	Southern Free-tail Bat
	Mormopterus species 4	South-western Free-tail Bat
Vespertilionidae	*Chalinolobus gouldii*	Gould's Wattled Bat
	Chalinolobus morio	Chocolate Wattled Bat
	Nyctophilus geoffroyi	Lesser Long-eared Bat
	Nyctophilus gouldi	Gould's Long-eared Bat
	Nyctophilus major	Greater Long-eared Bat
	Scotorepens balstoni	Inland Broad-nosed Bat
	Vespadelus baverstocki	Inland Forest Bat

Family	Species	Common Name
	Vespadelus regulus	Southern Forest Bat
Dasyuridae	*Antechinomys laniger*	Kultarr
	Ningaui ridei	Wongai Ningaui
	Ningaui yvonneae	Mallee Ningaui
	Pseudantechinus woolleyae	Woolley's False Antechinus
	Sminthopsis crassicaudata	Fat-tailed Dunnart
	Sminthopsis dolichura	Little Long-tailed Dunnart
	Sminthopsis gilberti	Gilbert's Dunnart
	Sminthopsis hirtipes	Hairy-footed Dunnart
	Sminthopsis longicaudata	Long-tailed Dunnart
	Sminthopsis macroura	Stripe-faced Dunnart
	Sminthopsis ooldea	Ooldea Dunnart
Myrmecobiidae	*Myrmecobius fasciatus*	Numbat
Burramyidae	*Cercartetus concinnus*	Southwestern Pygmy Possum
Macropodidae	*Macropus fuliginosus*	Western Grey Kangaroo
	Osphranter robustus	Euro
	Osphranter rufus	Red Kangaroo
Phalangeridae	*Trichosurus vulpecula*	Common Brushtail Possum
Potoroidae	*Bettongia lesueur*	Burrowing Bettong
Leporidae	*Oryctolagus cuniculus*	European Rabbit
Tachyglossidae	*Tachyglossus aculeatus*	Short-beaked Echidna
	Macrotis lagotis	Bilby
Equidae	*Equus asinus*	Donkey
	Equus caballus	Domestic Horse
Muridae	*Mus musculus*	House Mouse
	Notomys alexis	Spinifex Hopping Mouse
	Notomys mitchellii	Mitchell's Hopping Mouse
	Pseudomys albocinereus	Ash-grey Mouse
	Pseudomys bolami	Bolam's Mouse
	Pseudomys hermannsburgensis	Sandy Inland Mouse

Table 7. Reptile species recorded in areas adjacent to the project area

Family	Species	Common Name
Agamidae	*Ctenophorus caudicinctus*	Ring-tailed Dragon
	Ctenophorus cristatus	Crested Dragon
	Ctenophorus fordi	Mallee Dragon
	Ctenophorus inermis	Military Dragon
	Ctenophorus isolepis	Crested Dragon
	Ctenophorus maculatus	Spotted Dragon
	Ctenophorus nuchalis	Central Netted Dragon
	Ctenophorus ornatus	Ornate Crevice Dragon
	Ctenophorus pictus	Painted Dragon
	Ctenophorus reticulatus	Western Netted Dragon
	Ctenophorus salinarum	Saltpan Dragon
	Ctenophorus scutulatus	Lozenge-marked Dragon
	Diporiphora amphiboluroides	Mulga Dragon
	Moloch horridus	Thorny Devil
	Pogona minor	Dwarf Bearded Dragon
	Tympanocryptis cephalus	Pebble Dragon
Boidae	*Antaresia stimsoni*	Stimson's Python
	Morelia spilota	Carpet Python
Carphodactylidae	*Nephrurus laevissimus*	Smooth Knob-tail
	Nephrurus vertebralis	Midline Knob-tail
	Nephrurus wheeleri	Banded Knob-tail
	Underwoodisaurus milii	Barking Gecko
Diplodactylidae	*Amalosia reticulata*	Reticulated Velvet Gecko
	Diplodactylus conspicillatus	Fat-tailed Diplodactylus
	Diplodactylus granariensis	Wheat-belt Stone Gecko
	Diplodactylus pulcher	Fine-faced Gecko
	Hesperoedura reticulata	Reticulated Velvet Gecko
	Lucasium damaeum	Beaded Gecko
	Lucasium maini	Main's Ground Gecko
	Lucasium squarrosum	Mottled Ground Gecko

Family	Species	Common Name
	Strophurus assimilis	Goldfields Spiny-tailed Gecko
	Strophurus ciliaris	Spiny-tailed Gecko
	Strophurus elderi	Jewelled Gecko
	Strophurus intermedius	Southern Spiny-tailed Gecko
	Strophurus strophurus	Western Spiny-tailed Gecko
	Strophurus wellingtonae	Western Shield Spiny-tailed Gecko
Elapidae	*Acanthophis pyrrhus*	Desert Death Adder
	Brachyurophis fasciolata	Narrow-banded Burrowing Snake
	Brachyurophis semifasciata	Half-girdled Snake
	Demansia psammophis	Yellow-faced Whipsnake
	Elapognathus coronatus	Crowned Snake
	Furina ornata	Orange-naped Snake
	Neelaps bimaculatus	Black-naped Burrowing Snake
	Parasuta gouldii	Gould's Snake
	Parasuta monachus	Monk Snake
	Pseudechis australis	Mulga Snake
	Pseudechis butleri	Spotted Mulga Snake
	Pseudonaja mengdeni	Gwardar
	Pseudonaja modesta	Ringed Brown Snake
	Simoselaps bertholdi	Jan's Banded Snake
	Suta fasciata	Rosen's Snake
	Suta suta	Curl Snake
Gekkonidae	*Christinus marmoratus*	Marbled Gecko
	Gehyra punctata	Spotted Dtella
	Gehyra purpurascens	Purplish Dtella
	Gehyra variegata	Tree Dtella
	Gehyra xenopus	Crocodile-faced Dtella
	Heteronotia binoei	Bynoe's Prickly Gecko
	Rhynchoedura ornata	Western Beaked Gecko
Pygopodidae	*Aprasia picturata*	Black-headed Worm-lizard
	Delma australis	Marble-faced Delma

Family	Species	Common Name
	Delma butleri	Unbanded Delma
	Delma fraseri	Fraser's Delma
	Delma nasuta	Sharp-snouted Delma
	Lialis burtonis	Burton's Snake-lizard
	Pygopus lepidopodus	Common Scaly-foot
	Pygopus nigriceps	Western Hooded Scaly-foot
Scincidae	*Cryptoblepharus buchananii*	Buchanan's Snake-eyed Skink
	Ctenotus atlas	Southern Mallee Ctenotus
	Ctenotus brooksi	Wedgsnout Ctenotus
	Ctenotus calurus	Blue-tailed Finesnout Ctenotus
	Ctenotus greeri	Spotted-necked Ctenotus
	Ctenotus hanloni	Nimbel Ctenotus
	Ctenotus helenae	Clay-soil Ctenotus
	Ctenotus leae	Ornage-tailed Finesnout Ctenotus
	Ctenotus leonhardii	Leonhardi's Ctenotus
	Ctenotus pantherinus	Leopard Skink
	Ctenotus quattuordecimlineatus	Fourteen-lined Ctenotus
	Ctenotus schomburgkii	Schomburgk's Ctenotus
	Ctenotus severus	Stern Ctenotus
	Ctenotus uber	Spotted Ctenotus
	Ctenotus xenopleura	Wide-striped Ctenotus
	Cyclodomorphus branchialis	Common Slender Bluetongue
	Cyclodomorphus melanops	Spinifex Slender Bluetongue
	Egernia depressa	Pygmy Spiny-tailed Skink
	Egernia formosa	Goldfields Crevice-skink
	Egernia napoleonis	South-western Crevice-skink
	Eremiascincus richardsonii	Broad-banded Sand Swimmer
	Hemiergis initialis	South-western Earless Skink
	Lerista desertorum	Central Desert Robust Slider
	Lerista distinguenda	South-western Orange-tailed Slider
	Lerista kingi	King's Slider

Family	Species	Common Name
	Lerista lineopunctulata	Dotted-line Robust Slider
	Lerista macropisthopus	Unpatterned Robust Slider
	Lerista picturata	Southern Robust Slider
	Lerista timida	Timid Slider
	Liopholis inornata	Desert Skink
	Liopholis striata	Nocturnal Desert Skink
	Menetia greyii	Common Dwarf Skink
	Morethia adelaidensis	Saltbush Morethia Skink
	Morethia butleri	Woodland Morethia Skink
	Tiliqua multifasciata	Centralian Blue-tongued Lizard
	Tiliqua occipitalis	Western Blue-tongued Lizard
	Tiliqua rugosa	Bobtail
Typhlopidae	*Anilios australis*	Austral Blind Snake
	Anilios bicolor	Dark-spined Blind Snake
	Anilios bituberculatus	Prong-snouted Blind Snake
	Anilios hamatus	Pale-headed Blind Snake
	Anilios waitii	Waite's Blind Snake
Varanidae	*Varanus caudolineatus*	Stripe-tailed Monitor
	Varanus eremius	Pygmy Desert Monitor
	Varanus giganteus	Perentie
	Varanus gouldii	Gould's Goanna
	Varanus panoptes	Yellow-spotted Monitor
	Varanus tristis	Black-headed Monitor

4.3 CONSERVATION SIGNIFICANT FAUNA

Conservation significant fauna are protected by the Commonwealth *Environment Protection and Biodiversity Conservation Act* (*EPBC Act 1999*), and this list includes species covered by international treaties such as the Japan-Australia Migratory Bird Agreement (JAMBA) and China-Australia Migratory Bird Agreement (CAMBA) and the Western Australia (WA) *Biodiversity Conservation Act 2016* (*BC Act 2016*) The *BC Act 2016* provides for the publishing of the *Wildlife Conservation (Specially Protected Fauna) Notice* that lists species under multiple categories. In addition, DBCA maintains a list of fauna that require monitoring under four priorities based on the current knowledge of their distribution, abundance and threatening processes. The *EPBC Act 1999* and *BC Act 2016* imply legislative requirements for the management of anthropogenic impacts to minimise the effects of disturbances on species and their habitats. Priority species have no statutory protection, other than the DBCA wishes to monitor potential impacts on these species. Environmental consultants and proponents of developments are encouraged to avoid and minimise impacts on these species. Definitions of the significant fauna under the WA *BC Act* are provided in Appendix C.

Shorebirds, waders and marine migratory species have been excluded for this assessment as there is no suitable habitat for these species in or near the project area.

No threatened species of fauna are likely to be present in the project area, but one specially protected species may infrequently be present and there is a low possibility that two migratory species of birds identified under the *EPBC Act 1999* potentially occur in the project area or surrounds. The following is an assessment of the likelihood of each of the species listed in Table 8 being found in the project area.

Table 8. Assessment of the potential impact on conservation significant fauna that could occur in the bioregion

Species	DBCA Schedule / Priority	Status under Commonwealth EPBC Act	Comment on the potential impact on species
Night Parrot *Pezoporus occidentalis*	Critically Endangered	Endangered	Highly unlikely to be in the project area, due a lack of suitable habitat, so the potential for impact on this species is low.
Sandhill Dunnart *Sminthopsis psammophila*	Endangered	Endangered	Not present in the project area, so there will be no impact on this species.
Malleefowl *Leipoa ocellata*	Vulnerable	Vulnerable	Not present in the project area, so there will be no impact on this species.
Chuditch *Dasyurus geoffroii*	Vulnerable	Vulnerable	Not present in the project area, so there will be no impact on this species.
Grey Falcon *Falco hypoleucos*	Vulnerable	Vulnerable	Highly unlikely to be in the project area
Princess Parrot *Polytelis alexandrae*	Priority 4	Vulnerable	May very infrequently be seen in the region, however, clearing vegetation is unlikely to impact on this species.
Oriental Plover *Charadrius veredus*	Migratory	Migratory	Unlikley to be present in the project area so the potential for impact on this species is low.
Fork-tailed Swift *Apus pacificus*	Migratory	Migratory	May very infrequently be seen in the area, however, clearing vegetation is unlikely to impact on this species.
Grey Wagtail *Motacilla cinerea*	Migratory	Migratory	Highly unlikely to be seen in the project area, so the potential for impact on this species is low.
Yellow Wagtail *Motacilla flava*	Migratory	Migratory	Highly unlikely to be seen in the project area, so the potential for impact on this species is low.
Peregrine Falcon *Falco peregrinus*	Other specially protected		May infrequently be seen in the area; however, clearing vegetation is unlikely to impact on this species.
Woma python *Aspidites ramsayi*	P1		Highly unlikely to be seen in the project area, so the potential for impact on this species is low.
Mulgara *Dasycercus blythi / cristicauda*	Priority 4	Vulnerable	Highly unlikely to be in the project area, due a lack of suitable habitat, so the potential for impact on this species is low.
Long-tailed Dunnart *Sminthopsis longicaudata*	P4		Unlikley to be present in the project area due to a lack of suitable habitat.

Night Parrot (*Pezoporus occidentalis*) – Critically endangered under the WA *BC Act 2016* and endangered under the *EPBC Act 1999*

The Night Parrot was probably originally distributed over much of the semi-arid and arid Australia (Garnett et al. 2011, Threatened Species Scientific Committee 2016). Sightings in north-west Queensland in the early 1990s were in a broad cross section of the habitats available (Garnett et al. 1993). There have been recent sightings in the Pilbara in 1980, 2005 and 2017, central WA in 1979, north-eastern South Australia in 1979, western Queensland (including Pullen-Pullen-Mt Windsor-Diamantina population) in 1980, 1990, 1993, 2006 and 2013-17 (Davis and Metcalf 2008, Garnett et al. 2011, Palaszxzuk and Miles 2017), Pilbara in 2017 (Jones 2017) and near Lake Eyre in 2017 (McCarthy 2017). Garnett et al. (2011) suggested that there were between 50-250 mature individuals in less than 5% of its previous range.

Wilson's (1937) summary of observations provided information on the early records of Night Parrots' preferred habitat and breeding sites. More recent information indicates its preferred habitat appears to be in *Triodia* grasslands, chenopod shrub lands, shrubby samphire and floristically diverse habitats dominated by large-seeded species (Threatened Species Scientific Committee 2016, McCarthy 2017, Murphy et al. 2017b). It nests under *Triodia* and has a runway and a tunnel entrance with an apron of dead *Triodia* sp. leaves, and it has clutches of two to four sub-elliptical, white eggs with a lustrous appearance (Murphy et al. 2017a). Breeding

followed significant rains in March for the observations in Pullen-Pullen Reserve, but it is thought that breeding generally occurs between April and October (Murphy et al. 2017a).

As there are no recent Night Parrot records near the project area, and the habitat in the project area is not suitable for Night Parrots, so it is highly unlikely that they are present in the project area.

Malleefowl (*Leipoa ocellata*) – Vulnerable under the *BC Act 2018* and *EPBC Act 1999*

Malleefowl have been found in mallee regions of southern Australia from approximately the 26th parallel of latitude southwards. Malleefowl are now only found throughout these regions in fragmented patches of dense vegetation due to clearing of habitat for agriculture, increased fire frequency, competition with exotic herbivores (sheep, rabbits, cattle, goats) and kangaroos, predation by foxes and cats, inbreeding as a result of fragmentation and possibly hunting for food.

There are no Malleefowl mounds or tracks in the project area, and very little habitat that is suitable for Malleefowl, so it is highly unlikely that they are in the project area.

Chuditch (*Dasyurus geoffroii*) – Vulnerable under the *BC Act 2016* and *EPBC Act 1999*

The Chuditch is the largest extant carnivorous marsupial in WA. It is usually active from dusk to dawn. Formally known from over 70% of Australia, the Chuditch now has a patchy distribution throughout the Jarrah forest and mixed Karri/Marri/Jarrah forest of south-west WA and other isolated areas. Chuditch are solitary animals for most of their life and den in hollow logs, burrows, culverts, etc. and have also been recorded in tree hollows and rock cavities. Chuditch are opportunistic feeders, and forage primarily on the ground at night. Their diet can include other mammals, birds, lizards, bird and reptile eggs but the majority is a mixture of large invertebrates (e.g. spiders, scorpions and crickets).

None of the fauna surveys in the adjacent areas have recorded the presence of Chuditch, much of the habitat in the project area is not suitable and the abundance of feral predators indicates that it is highly unlikely that they would be present in the project area.

Grey Falcon (*Falco hypoleucos*) – Vulnerable under the *BC Act 2016* and *EPBC Act 1999*.

This is Australia's rarest falcon, and it is mostly found in areas of less than 500mm rainfall south of latitude 26°S in Western Australia (Threatened Species Scientific Committee 2020). It is mostly found in timbered lowland plains, particularly *Acacia* shrublands that are crossed by tree-lined water courses (Threatened Species Scientific Committee 2020). However, this species has been observed in treeless areas and frequents tussock grassland and open woodland (Threatened Species Scientific Committee 2020).

This species was not seen during the site visit, has not been recorded in other fauna surveys in the project or adjacent areas, and if it was present, then would move away once disturbed.

Princess Parrot (*Polytelis alexandrae*) - Vulnerable species under the *EPBC Act 1999* and as a Priority 4 species with DBCA

Very little is known about the Princess Parrot, even the exact extent of its geographical distribution. The species is found mostly in the inland arid areas of Australia, and in Western Australia in the Gibson, Little Sandy and Great Victoria Deserts (1998, Pavey et al. 2014). However, they occasionally occurred in lightly wooded areas adjacent to the sandy deserts (e.g. see Moriarty 1972a). It is thought to be nomadic within the central desert regions of Australia, occupying arid shrub lands, particularly those dominated by Mulga, Desert Oak and spinifex. Due to the paucity of information on the species, accurate estimates of its population size are difficult, however, this species is probably threatened by habitat loss to agricultural practices and changes in fire regimes.

Dr S. Thompson sighted a single specimen of this parrot in a survey near the Wanjarri Nature Reserve in 2006 and Moriarty (1972b) also reported it in the same area, so it may occasionally be seen in the general area. However, the proposed vegetation clearing is unlikely to significantly impact on this species as it will readily move away to other areas if it is disturbed.

Oriental Plover (*Charadrius veredus*) - Migratory species under the *EPBC Act 1999* and the WA *BC Act 2018*

A migrant species with patchy distribution in Australia, the Oriental Plover is sparsely distributed across arid and semi-arid Australia but avoids truly desert regions. Its preferred habitat is dry plains. The species is under threat because of habitat reduction due to agriculture and changing fire regimes. This plover has not been recorded in the general area in any of the other regional surveys.

Terrestrial Ecosystems' assessment is that the Oriental Plover is unlikely to be seen in the project area, due to a lack of previous records in the general area.

Fork-tailed Swift (*Apus pacificus*) - Migratory species under the *EPBC Act 1999* and the WA *BC Act 2018*

This species breeds in the northeast and mid-east Asia and winters in Australia and southern New Guinea. It is a visitor to most parts of Western Australia, beginning to arrive in the Kimberley in late September, in the Pilbara in November and in the southwest land division in mid-December, and leaving by late April. The Fork-tailed Swift is an almost exclusively aerial species, foraging and sleeping on the wing. It rarely comes to earth, usually only for breeding. It is common in the Kimberley, uncommon to moderately common near northwest, west and southeast coasts and rare to scarce elsewhere. It is rarely seen in the Goldfields.

Terrestrial Ecosystems' assessment is that the Fork-tailed Swift may infrequently be seen in the project area. However, the proposed vegetation clearing is unlikely to significantly impact on this species as it will move away to other areas if it is disturbed, and it is an almost exclusively aerial species.

Grey Wagtail (*Motacilla cinerea*) - Migratory species under the *EPBC Act 1999* and *BC Act 2016*

The Grey Wagtail is a small yellow breasted bird with a grey back and head. Johnstone and Storr (2004) reported this migratory species as breeding in Palearctic from western Europe and north-west Africa to eastern Asia and wintering in Africa, south-east Asia, Indonesia, the Philippines, New Guinea and Australia. Its preferred habitat in Australia is banks and rocks in fast-running fresh water including rivers, streams and creeks where it feeds on insects. The Atlas of Living Australia records two sightings on the south-coast of Western Australia and none around the project area.

It is highly unlikely to be seen in the project area due to a lack of suitable habitat.

Yellow Wagtail (*Motacilla flava*) - Migratory species under the *EPBC Act 1999* and *BC Act 2016*

This bird breeds in far eastern Siberia and on Commander and Kurile Islands and winters from Myanmar and the Philippines south to northern Australia. It is a vagrant in southern Australia. It has a preference for damp short-grass flats, edges of swamps, bore overflows, grazed and mowed grass and irrigated areas (Johnstone and Storr 2004).

It is highly unlikely that this bird is present in the project area due to a lack of suitable habitat and the rarity of its presence in southern Australia.

Peregrine Falcon (*Falco peregrinus*) – Other specially protected under *BC Act 2016*

The Peregrine Falcon is uncommon, although widespread throughout much of Australia excluding the extremely dry areas and has a wide and patchy distribution. It shows habitat preference for areas near cliffs along coastlines, rivers and ranges and within woodlands along watercourses and around lakes. Nesting sites include ledges along cliffs, granite outcrops and quarries, hollow trees near wetlands and old nests of other

large bird species. There is no evidence to suggest any change in status in the last 50 years. The Peregrine Falcon has been seen in the Wanjarri Nature Reserve (Moriarty 1972b), at Honeymoon Well (Ninox Wildlife Consulting 1994), at Murrin Murrin (Ninox Wildlife Consulting 1998), at Cawse (Hart Simpson and Associates 2000) and at Mileura (Tingay and Tingay 1977), so they could infrequently be seen in the general area.

Terrestrial Ecosystems' assessment is that the Peregrine Falcon may infrequently be seen in the project area. However, the proposed developments are unlikely to significantly impact on this species as it will move away to other areas if it is disturbed.

Woma python (*Aspidites ramsayi*) – Priority 1 species with DBCA

The Woma Python was once found in a crescent shaped geographic distribution from Shark Bay to Kitchener, but it is distribution has been reduced to an area on the western Australian coast near Shark Bay, in the eastern section around Kitchener and a small population on the sand plain near Mt Walton, with rare individuals being occasionally recorded in the sand plain of the northern Goldfields.

Woma pythons are typically recorded in sand plain habitat, as they have a habit of burrowing into the ground and use burrows of other animals as retreat sites. There are no recent records of Woma Pythons around Menzies and given the highly disturbed nature of the project area, it is improbable that they are present in the project area.

Brush-tailed Mulgara (*Dasycercus blythi / cristicauda*) - Vulnerable species under the *EPBC Act 1999* and Priority 4 with the DBCA

Woolley (2005) has recently recognised two species of 'Mulgara'; *Dasycercus blythi* and *D. cristicauda*. *Dasycercus blythi* has a non-crested tail, two upper premolars and six nipples; *D. cristicauda* has a crested tail, three upper premolars and eight nipples. Both species potentially have overlapping distributions in arid Australia. Woolley (2005) suggested the common names for these two species be Brush-tailed Mulgara for *D. blythi* and Crest-tailed Mulgara for *D. cristicauda*. These two species can be sympatric in places, but probably utilise different parts of the habitat on a local scale when they are recorded in the same area. Currently, there are insufficient data to separate the spatial ecology, burrows and reproductive biology of these two species. Information that follows is based on what is known for 'Mulgara' without distinguishing between the species.

The reported distribution of Mulgara includes much of the inland spinifex covered sandy desert and spinifex vegetated areas in the Pilbara and northern Goldfields. Within these areas their distribution is patchy and it is most frequently confined to mature spinifex dominated habitat (Gibson and Cole 1992, Masters 2003, Masters et al. 2003, Thompson and Thompson 2007, 2008). In some areas, their relative abundance is positively associated with rainfall in the previous 12 to 24 months (Gibson and Cole 1992, Masters 1998, Dickman et al. 2001, Letnic and Dickman 2005) and recent burning of the spinifex does not seem to be sufficient to shift Mulgara out of an area (Thompson and Thompson 2007). Mulgara are generally sedentary in contrast with some other small dasyurids and have high site fidelity and a low propensity for dispersal once a home range has been established (Masters 1998, Dickman et al. 2001).

It is Terrestrial Ecosystems' view that Mulgara is unlikely of be found in the project area due to a lack of suitable habitat.

Long-tailed Dunnart (*Sminthopsis longicaudata*) – Priority 4 species with DBCA

Burbidge et al. (2008) summarised the Long-tailed Dunnart distribution as widely scattered in arid zone where it inhabits rugged rocky areas. They went on to suggest that its striated foot-pads, long tail and behaviour in captivity indicated that it was an active and capable climber. Specimens have been recorded in several rocky ranges in the Gibson Desert, West MacDonnell National Park, Murchison, Carnarvon Basin and the Pilbara. All previous capture sites for Long-tailed Dunnarts are within rugged rocky landscapes that support a low open

woodland or shrubland of Acacias (especially mulga) with an understorey of spinifex hummocks, and (occasionally) also perennial grasses and cassias.

Long-tailed Dunnarts have been caught at Mt Ida, Bottle Creek, Granny Smith (Terrestrial Ecosystems 2011), Murrin Murrin, Mt Mason (DBCA threatened species database search) and Mt Forrest (Harewood 2014a, Harewood 2014b). The low rocky ridges in the project area are small and isolated, so there is a very low possibility that they support Long-tailed Dunnarts.

4.4 RISK ASSESSMENT

Fauna surveys to support Environmental Impact Assessments (EIA) are part of the environmental risk assessment undertaken to consider what potential impacts a development might have on the biodiversity on a particular area and region. Potential impacts on fauna from the proposed development are identified and briefly described above. Tables 9, 10 and 11 provide a summary of the risk assessment associated with this project.

The assessment contained in Table 11 is supported by more detail discussion in sections above and the management recommendations below. Any risk assessment is a product of the likelihood of an impact occurring and the consequences of that impact. Likelihood and consequences are categorised and described below. These criteria do not fit all circumstances (e.g. adequacy of fauna survey data); however, they are useful in providing the reader with an appreciation of the level of likelihood and consequences of an event. The assessed risk level (likelihood x consequences) is then calculated as the overall risk for the development. This is followed by an assessment of the acceptability of the risk associated with each of the impacts. Disturbances and vegetation clearing have an impact on the fauna at multiple scales – site, local, landscape and regional. Each of these is considered in the risk assessment. This assessment should be considered in the context of the summary in Table 11.

Table 9. Fauna impact risk assessment descriptors

Likelihood		
Level	Description	Criteria
A	Rare	The environmental event may occur, or one or more conservation significant species may be present in exceptional circumstances.
B	Unlikely	The environmental event could occur, or one or more conservation significant species could be present at some time.
C	Moderate	The environmental event should occur, or one or more conservation significant species should be present at some time.
D	Likely	The environmental event will probably occur, or one or more conservation significant species will be present in most circumstances.
E	Almost certain	The environmental event is expected to occur, or one or more conservation significant species is expected be present in most circumstances.
Consequences		
Level	Description	Criteria
1	Insignificant	Insignificant impact on fauna of conservation significance or regional biodiversity, and the loss of individuals will be insignificant in the context of the availability of similar fauna or fauna assemblages in the area.
2	Minor	Impact on fauna localised and no significant impact on species of conservation significance in the project area. Loss of species at the local scale.
3	Moderate	An appreciable loss of fauna in a regional context or a limited impact on species of conservation significance in the project area.
4	Major	Significant impact on conservation significant fauna or their habitat in the project area and/or regional biodiversity and/or a significant loss in the biodiversity at the landscape scale.
5	Catastrophic	Loss of species at the regional scale and/or a significant loss of species categorised as 'vulnerable' or 'endangered' under the EPBC Act (1999) at a regional scale.
Acceptability of Risk		
Level of risk	Management Action Required	
Low	No action required.	
Moderate	Avoid if possible, routine management with internal audit and review of monitoring results annually.	
High	Externally approved management plan to reduce risks, monitor major risks annually with external audit and review of management plan outcomes annually. May a referral to the Commonwealth under the EPBC Act 1999.	
Extreme	Unacceptable, project should be redesigned or not proceed.	

Table 10. Levels of acceptable risk

		Likelihood				
		Rare or very low (A)	Unlikely or low (B)	Moderate (C)	Likely (D)	Almost certain (E)
Consequence	Insignificant (1)	Low	Low	Low	Low	Low
	Minor (2)	Low	Low	Low	Moderate	Moderate
	Moderate (3)	Low	Moderate	Moderate	High	High
	Major (4)	Moderate	Moderate	High	High	Extreme
	Catastrophic (5)	Moderate	High	High	Extreme	Extreme

Table 11. A risk assessment of the impact of ground disturbance activity on fauna

			Before management				With management		
	Potential impacts		Inherent risk			Risk controls	Residual risk		
Factor			Likelihood	Consequence	Significance		Likelihood	Consequence	Significance
Fauna survey data	Inadequate survey data to adequately assess the risks	Unknown loss of fauna, fauna of conservation significance, and fauna assemblages, and an incomplete fauna assessment.	B	2	Low				
	Inadequacy of comparative data	Limits on the availability of comparative data reduced the capacity to assess the uniqueness of the fauna assemblages in the project area.	B	2	Low				
Clearing vegetation	Loss of fauna habitat – local scale	Loss of terrestrial fauna in the project area.	E	2	Mod	Where possible, reduce the extent of clearing.	E	2	Mod
	Loss of fauna habitat – landscape scale	Loss of some fauna during vegetation clearing.	B	1	Low				
	Loss of fauna habitat – regional scale	Small loss of some fauna from the region.	B	1	Low				
	Loss of a threatened ecological fauna community	Loss of an undetected threatened ecological fauna community.	A	3	Low				
	Habitat fragmentation	Fauna movement restricted resulting in the death of fauna and a loss of biodiversity.	A	2	Low				
Death or loss of conservation significant fauna	Loss of a unique terrestrial fauna ecosystem	Loss of an ecosystem containing fauna with high species richness, high abundance and numerous top of the food chain predators.	A	2	Low				
	Peregrine Falcon	Loss of a Peregrine Falcon or small population of Peregrine Falcon	A	2	Low				
Human impacts	Increase or spread of weeds	Changed vegetation and a resulting loss of fauna habitat.	E	2	Mod	Implementation of a weed management plan.	D	2	Low
	Road kills	Animals being killed by vehicles as they cross roads	E	1	Low	Limiting vehicle speeds	E	1	Low
	Increase in feral fauna; specifically the fox, wild dog and cat	Increased predation on the native fauna	C	3	Mod	Implementation of a feral animal control program(s)	C	2	Low
	Dust	Increased potential for dust	E	2	Mod	Implementation of a dust management plan.	C	2	Low

5. DISCUSSION

5.1 ADEQUACY OF THE FAUNA SURVEY DATA FOR FAUNA HABITATS REPRESENTED IN THE PROJECT AREA

The EPA's (2020) Technical Guidance on terrestrial fauna surveys indicated that the type of survey should be determined based on:

- level of existing regional knowledge;
- type and comprehensiveness of recent local surveys;
- degree of existing disturbance or fragmentation at the regional scale;
- extent, distribution and significance of habitats;
- significance of species likely to be present;
- sensitivity of the environment to the proposed activities; and
- scale and nature of impact.

Fauna assessments of most value are the ones undertaken by Thompson (2004), Cowan and How (2004), Dell and How (1988), and Ninox Wildlife Consulting (1998). Taken together they provide a comprehensive list of the vertebrate fauna species potentially found in the project area.

Much of the project area has been disturbed by previous mining and anthropogenic activity with the consequence that a generic Detailed and Targeted survey of the project area is unlikely to provide additional information that would alter an assessment by government regulators and is therefore not required.

5.1.1 Amphibians

Frogs are normally only detected immediately after rainfall or around semi-permanent pools. The project area shows no sign of long-term pooling of surface freshwater water, other than in the mining pits which typically do not support amphibians. There are no conservation significant amphibians near the project area.

5.1.2 Reptiles

Typically, between 25 and 35 species of reptiles are caught in eucalypt or open mulga woodlands, or shrublands (Thompson et al. 2003, Cowan and How 2004, ATA Environmental 2007, Coffey Environments 2008, Terrestrial Ecosystems 2010) in this part of the goldfields. The spareness of the vegetation and lack of leaf litter for much of the project area would mean there is a lower abundance and probably fewer species than in the more vegetated areas. None of the species likely to be in the project area are of conservation significance.

Fauna habitats in the project area are expected to be like that in the adjacent areas, so the loss of reptiles during vegetation clearing is unlikely to be significant in a bioregional context.

5.1.3 Birds

The number of birds and bird species in the northern Goldfields fluctuates based on seasons and recent rainfall (Craig and Chapman 2003). The project area is likely to support a similar assemblage to that present in the adjacent areas. Birds of conservation significance potentially found in the area include the Peregrine Falcon, and the Princess Parrot. The Princess Parrot is nomadic and moves around the arid interior often in search of water and resources. It has infrequently been recorded in the general area and will readily move if disturbed. The Peregrine Falcon will normally have a very large home range in the Goldfields, and clearing a small section of the project area, particularly when similar habitat exists in the adjacent areas, is unlikely to significantly impact on this species. All birds will readily shift to other areas when there is a disturbance.

It is Terrestrial Ecosystems' view that the proposed additional vegetation clearing for the redevelopment of a mine and associated infrastructure is unlikely to significantly impact on the avian fauna of the bioregion.

5.1.4 Mammals

The number of small terrestrial mammals potentially caught in the project area would be low due the sparsely vegetated habitat. Although, records of Burrowing Bettongs (*Bettongia lesueur*) and Bilbies (*Macrotis lagotis*) are shown in the Atlas of Living Australia and the Western Australian Museum records, they are no longer present in this area, having been predated on by foxes, cats and wild dogs many years ago. The project area contains a few low rocky ridges, but they are not considered suitable habitat for the Priority 4 Long-tailed Dunnart as the areas are small and isolated.

5.2 BIODIVERSITY VALUE OF THE PROJECT AREA

An ecological assessment of a site should consider its biodiversity value at the genetic, species and ecosystem levels, and its ecological functional value at the ecosystem level. There are inadequate data to assess the ecological value at the genetic level.

Fauna habitat types represented in the project area are abundant and in similar condition in adjacent areas. Therefore, the fauna assemblage that is present in the project area will also be present and abundant in the adjacent areas. The available fauna survey data (Appendix B) provides a good indication of the vertebrate fauna that are potentially in the project area.

5.2.1 Ecological functional value at the ecosystem level

Vertebrate species potentially in the project area are wide-ranging and have been recorded in various other fauna surveys in the bioregion (Appendix B). There is likely to be a relatively low abundance of reptiles and mammals in the project area because of the prior disturbance and anthropogenic activity. A substantial section of the project area has been mined, explored and the disturbance that results from that mining and exploration is evident at multiple locations.

5.2.2 Maintenance of threatened ecological communities

No threatened ecological communities were identified in or near the project area.

5.2.3 Condition of fauna habitat

There are multiple areas of past mining activity, including large pits, waste dumps, the remains of built infrastructure and tracks that criss-cross much of the project area. Over a long period, introduced predators are likely to have been one of the most significant impacts on the vertebrate fauna in the project area. The uncleared fauna habitat of the project area is similar to that in the many square kilometres of adjacent habitat; therefore, clearing of the vegetation is unlikely to have a significant impact on the vertebrate fauna when considered in a bioregional context.

5.2.4 Ecological linkages

The project area does not provide an important ecological linkage or terrestrial fauna movement corridor.

5.2.5 Abundance and distribution of similar habitat in the adjacent areas

The fauna assemblage in the project area is like that in the many square kilometres of similar habitat in adjacent areas and the bioregion, so the loss of vegetation and the local vertebrate is unlikely to have a significant impact. However, there is a slowly growing cumulative impact when cattle grazing, mining and exploration activity are considered in the bioregion.

6. POTENTIAL IMPACTS

6.1 POTENTIAL IMPACTS ON FAUNA

Clearing of vegetation will potentially affect vertebrate fauna in numerous ways, including death/injury of fauna during clearing, grading and impacts with vehicles and the loss of habitat.

Although there are anticipated short term impacts on fauna, they are not considered to result in significant impacts on fauna habitat and fauna assemblages in a bioregional context in the longer term. The overall impact on fauna species and species of conservation significance will be minimal provided the recommended management procedures are implemented and adhered to.

The project area contains a few low rocky ridges, but these are generally isolated and therefore unlikely to support a population of Long-tailed Dunnarts. There are no other conservation significant terrestrial species likely to be recorded in the project area that would be impacted by vegetation clearing.

6.2 DIRECT IMPACTS

6.2.1 Animal deaths during the clearing process and displacement of fauna

Clearing vegetation and activities associated with the mining development will result in the loss of small fauna that retreat to burrows, such as reptiles and mammals. Nocturnal species are unlikely to be active when most of the land clearing is taking place which will inevitably result in these individuals being killed or injured in their burrows or as they attempt to escape. Larger terrestrial animals and avian species will most often move to adjacent areas. These species will be required to establish new activity areas and home ranges, and this could result in the temporary displacement of resident species, however, this loss of fauna is unlikely to have a significant impact when considered in a bioregional context.

6.2.2 Reduction or loss of activity areas and closure of burrows

Clearing vegetation and associated mining activities are likely to destroy reptile and mammal burrows or foraging habitat that are currently in use or could be used again. Clearing vegetation in areas that form part of the activity area of individuals has the potential to force these animals into adjacent areas. These areas may offer fewer resources placing individuals under survival pressure. It could also cause individuals to move into the territories of other individuals increasing competition for resources. Forced relocations could increase the possibility of predation.

6.3 INDIRECT IMPACTS

In addition to the obvious impact of vegetation clearing there can be an equally significant or greater impact in the adjacent areas because of 'edge effects'. Edge effects can lead to the disruption of ecological processes such as predation and dispersal, animal movements and can change assemblage structure. The consequence is that the impact area will always be much larger than the cleared area. Vehicle tracks and areas cleared for mining activity also have the propensity to develop weed infestations which can impact on natural fauna habitats.

There are numerous potential threats associated with vegetation clearing and the construction of infrastructure that could have an impact on the vertebrate fauna in the project area. Some of these are discussed below.

6.3.1 Habitat fragmentation

In addition to vegetation clearing, infrastructure including tracks, has the potential to fragment habitat. Cleared vegetation that fragments fauna habitats and partition existing fauna activity areas can isolate sections of established faunal communities and may alter long and medium-term patterns of movement around established home ranges particularly for small mammals and reptiles. A reduction in the population due to vegetation clearing would be difficult to detect given our current knowledge of the spatial ecology for most of the small mammals known to be in the area.

6.3.2 Introduced fauna and weeds

An increase in human activity is often associated with an increase in the abundance of introduced species such as the house mouse (*Mus musculus*), foxes (*Vulpes vulpes*), cat (*Felis catus*) and wild dogs (*Canis lupus*). This increase may be due to a decline in habitat health, increased road kills, poor disposal of waste and easier access to areas via tracks.

House mice, foxes, cats and wild dogs are known to be established in the area. In many situations they have become a 'naturalised' species in the Australian bush. Increases in fox, dog or cat numbers can have a detrimental impact on native fauna because they predate on and compete with native species, severely disrupting the natural balance.

Infrastructure known to support feral species, such as rubbish disposal sites and bins, should be managed to minimise increases in these populations.

Introduced plant species can successfully and rapidly invade areas of cleared native vegetation or otherwise disturbed by humans. Introduced plant species may replace native species that provide shelter or foraging areas for native fauna. Major changes to the structure of vegetation will alter the fauna habitat and consequently may influence fauna species composition. Preparing and implementing a weed management plan will largely reduce their threat to native fauna species.

6.3.3 Road fauna deaths

An increase in road fauna deaths is likely to occur where new roads are constructed or upgraded affecting kangaroos, nocturnal birds and ground dwelling large carnivorous predators. Species such as goannas and raptors are attracted to carrion on road verges and therefore, there is an increased propensity for these species to be killed by vehicles.

6.3.4 Fire

Increased human activity is often associated with an altered fire regime which can lead to a degradation of natural ecosystems. Fire has been identified as one of the threatening processes for some conservation significant species as many small mammal and bird species rely on long unburnt vegetation.

Fires are unlikely to be a significant threat to native fauna species near the project area due to the sparseness of the vegetation.

6.3.5 Anthropogenic activity

Unnatural noises, vibrations, artificial light sources, and vehicle and human movement in an area may be sufficient to force individuals or fauna species to move from adjacent areas or alter their activity periods. This

form of disturbance is likely to occur during the vegetation clearing and when mining activity commences. The overall impact is likely to be confined to a relatively small area and is unlikely to be a significant impact.

6.3.6 Dust

Dust generated from shifting topsoil and spoil and vehicle traffic can potentially degrade surrounding vegetation, reducing its ability to absorb sunlight, and influencing photosynthetic rates. Degradation of these areas may potentially render habitat unsuitable for fauna. Dust suppression and management programs are an essential component of minimising impacts on fauna in areas adjacent to the mine. An effective dust management and monitoring program is required.

6.4 NATIVE VEGETATION CLEARING PRINCIPLES

The *Environmental Protection Act (1986)* provides criteria to judge the potential impact of a development on clearing native vegetation on flora and fauna. These criteria have been listed below with a response to indicate how clearing of the vegetation in the project area might be judged against these principles as they relate to fauna and fauna assemblages (Table 12). Where possible, native vegetation should not be cleared if any of the following principles are compromised.

Table 12. Assessment of impact on fauna and fauna assemblages using the native vegetation clearing principles

Principle	Response
It comprises a high level of biological diversity.	Clearing vegetation will not comprise a high level of biodiversity.
It comprises the whole or a part of, or is necessary for the maintenance of, a significant habitat for fauna indigenous to Western Australia.	Clearing the vegetation will not result in the loss of significant habitat for indigenous fauna.
It includes, or is necessary for the continued existence or, rare flora.	N/A
It comprises the whole or a part of, or is necessary for the maintenance of, a threatened ecological community.	The area does not contain a threatened ecological community.
It is significant as a remnant of native vegetation in an area that has been extensively cleared.	The area is not a remnant, and the vegetation clearing will not create a remnant.
It is growing in, or in association with, an environment associated with a watercourses or wetland.	The proposed vegetation clearing and mine are not in a water course or wetland.
The clearing of the vegetation is likely to cause appreciable land degradation.	N/A
The clearing of the vegetation is likely to have an impact on the environmental values of any adjacent or nearby conservation area.	Clearing of vegetation is unlikely to impact on the environmental values of the bioregion.
The clearing of the vegetation is likely to cause deterioration in the quality of surface or underground water.	N/A
The clearing of the vegetation is likely to cause, or exacerbate the incidence of flooding.	N/A

6.5 REFERRAL UNDER THE EPBC ACT

The proposed project is unlikely to significantly impact on a conservation significant species, so a referral under the *EPBC Act* is not required.

7. SUMMARY

The Menzies Gold project area assessed was 1,565ha and is immediately west and south-west of the Menzies town site in the northern Goldfields. This Basic vertebrate fauna survey and risk assessment provides an indication of the vertebrate species potentially in the project area and surrounds, and indicates the potential impacts and consequences from developing the historical mining operations.

There are seven broad fauna habitats in the entire project area:

- Bushy shrubland;
- Casuarina woodland;
- Eucalypt woodland;
- Open grassland;
- Shrubland on a ridge;
- Shrubland; and
- Previously disturbed areas.

Much of the project area is highly disturbed with multiple mining pits, waste dumps, vehicles tracks and built infrastructure. The density of the vegetation varies appreciably across the project area with many patches of bare ground.

The fauna habitats in the project area are like that in adjacent areas, with the consequence that a loss of this habitat is unlikely to have a significant impact on the vertebrate fauna in a bioregional context.

The project area contains some low rocky ridges, but they are small and isolated, so it is unlikely that they support the Priority 4 Long-tailed Dunnart.

There is no requirement for an EPBC referral as the reopening and development of a mine will not significantly impact on conservation significant species.

8. MANAGEMENT STRATEGIES

8.1.1 Induction and awareness

All contractors and people involved in exploration or mining activities should be made aware of the possible presence and issues associated with terrestrial fauna in the area through the induction process.

Recommendation 1: An induction program that includes a component on managing fauna is a mandatory component of working on the Menzies Gold project.

8.1.2 Minimising secondary impacts to the habitat

Pets and feral animals have the potential to impact on fauna. Pets should not be permitted on site and feral and pest fauna numbers monitored and controlled. All rubbish likely to attract animals should be suitably contained and disposed of so as not to encourage the feeding of fauna around the site.

Recommendation 2: Pets are not permitted on site.

Recommendation 3: All waste and rubbish be contained in bins and regularly removed from site or buried so it is unavailable to pest species.

Recommendation 4: Feeding of native fauna should be actively discouraged.

8.1.3 Uncapped exploration drill holes

Over an extended exploration period, caps on some drill holes have been displaced or removed and others may never have been capped. When the drill hole opening is at ground level, then they become a trap for vertebrate fauna from which there is no escape.

Recommendation 5: A log of the location of all drill holes in maintained along with the person responsible for securely capping the hole.

8.1.4 Feral pest species

Feral pest species such as wild dogs, foxes, feral cats and rabbits negatively impact on native fauna. Land managers have a responsibility to manage some of these feral pests, so when the mine becomes operational, feral pest management should be included in the fauna management plan for the mining operations.

Recommendation 6: A feral and pest management program is implemented for the project area.

9. REFERENCES

ATA Environmental. 2007. Level 2 Vertebrate Fauna Assessment, Honeymoon Well, Wiluna. Perth.

Bell, D. T., R. C. Bell, and W. A. Loneragan. 2007. Winter bird assemblages across an arid gradient in south-west Western Australia. Journal of the Royal Society of Western Australia **90**:219-227.

Burbidge, A. A., N. L. McKenzie, and P. J. Fuller. 2008. Long-tailed Dunnart *Sminthopsis longicaudata*. Pages 148-150 *in* S. van Dyck and R. Strahan, editors. The Mammals of Australia. Reed New Holland, Sydney.

Coffey Environments. 2008. Level 2 Fauna Assessment for the Duketon Gold Project.

Cowan, M. 2003. Murchison 1 (MUR1 - East Murchison subregion). Pages 466-479 *in* N. L. McKenzie, J. E. May, and S. McKenna, editors. Bioregional Summary of the 2002 Biodiversity Audit for Western Australia. Department of Conservation and Land Management, Perth.

Cowan, M. A., and R. A. How. 2004. Comparisons of ground vertebrate assemblages in arid Western Australia in different seasons and decades. Records of the Western Australian Museum **22**:91-100.

Craig, M. D., and A. Chapman. 2003. Effects of short-term drought on the avifauna of Wanjarri Nature Reserve: What do they tell us about drought refugia? Journal of the Royal Society of Western Australia **86**:133-137.

Davis, R. A., and B. M. Metcalf. 2008. The Night Parrot (*Pezoporus occidentalis*) in northern Western Australia: a recent sighting from the Pilbara region. Emu **108**:233-236.

Dell, J., R. A. How, A. V. Milewski, and G. J. Keighery. 1988. The biological survey of the eastern goldfields of Western Australia Part 5: Edjudina - Menzies Study Area. Records of the Western Australian Museum **Supplement No. 31**:38-69.

Dickman, C. R., A. S. Haythornthwaite, G. H. McNaught, P. S. Mahon, B. Tamayo, and M. Letnic. 2001. Population dynamics of three species of dasyurid marsupials in arid central Australia: a 10 year study. Wildlife Research **28**:493-506.

ecologia Environment. 2007. Jump Up Dam Fauna Assessment.

Environmental Protection Authority. 2020. Technical Guidance – Terrestrial vertebrate fauna surveys for environmental impact assessment. Western Australia.

Garnett, S., G. Crowley, R. Duncan, N. Baker, and P. Doherty. 1993. Notes on live Night Parrot sightings in north-western Queensland. Emu **93**:292-296.

Garnett, S. T., J. K. Szabo, and G. Dutson. 2011. The Action Plan for Australian Birds 2010. CSIRO, Collingwood, Melbourne.

Gibson, D. F., and J. R. Cole. 1992. Aspects of the ecology of the Mulgara, *Dasycercus cristicauda*, (Marsupialia: Dasyuridae) in the Northern Territory. Australian Mammalogy **15**:105-112.

Harewood, G. 2014a. Seasonal Fauna Surveys (Level 2 - Phase 1 to 4). Perth.

Harewood, G. 2014b. Seasonal Fauna Surveys Mount Forrest Iron Project. SF 009260, Bunbury.

Hart Simpson and Associates. 2000. Anaconda Nickel Ltd, Cawse Expansion Project, Fauna Survey. Perth.

Johnstone, R. E., and G. M. Storr. 1998. Handbook of Western Australian Birds. Volume I - Non-Passerines (Emu to Dollarbird). Western Australian Museum, Perth.

Johnstone, R. E., and G. M. Storr. 2004. Handbook of Western Australian birds, Volume II passerines (Blue-winged Pitta to Goldfinch). Western Australian Museum, Perth.

Jones, A. 2017. Night parrot sighting in Western Australia shocks birdwatching world. ABC News.

Keith Lindbeck and Associates. 2012. Central Yilgarn Iron Project (CYIP) Fauna Assessment. Perth.

Letnic, M., and C. R. Dickman. 2005. The responses of small mammals to patches regenerating after fire and rainfall in the Simpson Desert, central Australia. Austral Ecology **30**:24-39.

Malnic, J. 1997. Uncapped drill holes are silent killers. Australia's Mining Monthly **March**:16.

Masters, P. 1998. The Mulgara *Dasycercus cristicauda* (Marsupialia: Dasyuridae) at Uluru National Park, Northern Territory. Australian Mammalogy **20**:403-407.

Masters, P. 2003. Movement patterns and spatial organisation of the mulgara, *Dasycercus cristicauda* (Marsupialia: Dasyuridae), in central Australia. Wildlife Research **30**:339-344.

Masters, P., C. R. Dickman, and M. Crowther. 2003. Effects of cover reduction on Mulgara *Dasycercus cristicauda* (Marsupialia: Dasyuridae), rodent and invertebrate populations in central Australia: Implications for land management. Austral Ecology **28**:658-665.

McCarthy, M. 2017. Night parrot feather discovery proves Australia's most elusive bird is alive in South Australia. ABC News.

Moriarty, T. K. 1972a. Birds of Wanjarri, W.A. (27°25'S, 120°40'E). The Emu **72**:1-7.

Moriarty, T. K. 1972b. Birds of Wanjarri, W.A. (27°25'S, 120°40'E). Emu **72**:1-7.

Murphy, S. A., J. J. Austin, R. K. Murphy, J. Silcock, L. Joseph, S. T. Garnett, N. P. Leseberg, J. E. M. Watson, and A. H. Burbidge. 2017a. Observations on breeding Night Parrots (*Pezoporus occidentalis*) in western Queensland. Emu **117**:107-113.

Murphy, S. A., J. Silcock, R. Murphy, J. Reid, and J. J. Austin. 2017b. Movements and habitat use of the night parrot *Pezoporus occidentalis* in south-western Queensland. Austral Ecology.

Ninox Wildlife Consulting. 1994. A Fauna Assessment of the Honeymoon Well Project Area. April and September 1993. Perth.

Ninox Wildlife Consulting. 1998. A Vertebrate Fauna Survey of the Murrin Murrin Expansion Project. Perth.

Palaszxzuk, A., and S. Miles. 2017. New night parrot community discovered in central west Queensland.

Pavey, C. R., C. E. M. Nano, J. R. Cole, P. J. McDonald, P. Nunn, A. Silcocks, and R. H. Clarke. 2014. The breeding and foraging ecology and abundance of the Princess Parrot (*Polytelis alexandrae*) during a population irruption. Emu:NULL.

Storr, G. M., L. A. Smith, and R. E. Johnstone. 1983. Lizards of Western Australia. II: Dragons and Monitors. Western Australian Museum, Perth, Western Australia.

Storr, G. M., L. A. Smith, and R. E. Johnstone. 1990. Lizards of Western Australia. III: Geckos and Pygopods. Western Australian Museum, Perth.

Storr, G. M., L. A. Smith, and R. E. Johnstone. 1999. Lizards of Western Australia. I: Skinks. Western Australian Museum, Perth.

Storr, G. M., L. A. Smith, and R. E. Johnstone. 2002. Snakes of Western Australia. Western Australian Museum, Perth.

Terrestrial Ecosystems. 2010. Level 2 Fauna Risk Assessment for the Garden Well Project Area. Perth.

Terrestrial Ecosystems. 2011. Targeted Survey for Long-tailed Dunnarts for the Granny Deeps Project Area. Perth.

Thompson, G. G., and S. A. Thompson. 2007. Shape and spatial distribution of Mulgara (*Dasycercus cristicauda*) burrows, with comments on their presence in a burnt habitat and a translocation protocol. Journal of the Royal Society of Western Australia **90**:195-202.

Thompson, G. G., and S. A. Thompson. 2008. Abundance and spatial distribution of five small mammals at a local scale. Australian Mammalogy **30**:65-70.

Thompson, G. G., S. A. Thompson, P. C. Withers, and E. R. Pianka. 2003. Diversity and abundance of pit-trapped reptiles in Australian arid and mesic habitats: Biodiversity for environmental impact assessments. Pacific Conservation Biology **9**:120-135.

Thompson, S. A. 2004. Mine site rehabilitation index using reptile assemblage as a bio-indicator. PhD. Edith Cowan University, Perth.

Thompson, S. A., and G. G. Thompson. 2010. Terrestrial Vertebrate Fauna Assessments for Ecological Impact Assessment. Terrestrial Ecosystems, Perth.

Threatened Species Scientific Committee. 2016. Conservation Advice *Pezoporus occidentalis* Night Parrot. Canberra.

Threatened Species Scientific Committee. 2020. Conservation Advice *Falco hypoleucos* Grey Falcon. Canberra.

Tingay, A., and S. R. Tingay. 1977. A Vertebrate Fauna Survey of Yeelirrie Station, Western Australia. Perth.

Tyler, M. J., L. A. Smith, and R. E. Johnstone. 2000. Frogs of Western Australia. Western Australian Museum, Perth.

Van Dyck, S., and R. Strahan. 2008. The Mammals of Australia. Reed New Holland, Sydney.

Western Botanical. 2021. Detailed Flora and Vegetation Assessment of the Menzies Gold Project for Kingwest Resources Ltd. Perth.


Wilson, H. 1937. Notes on the Night Parrot, with references to recent occurrences. Emu **37**:79-87.

Woolley, P. A. 2005. The species of *Dasycercus* Peters, 1875 (Marsupialia: Dasyuridae). Memoirs of Museum Victoria **62**:213-221.

Figures

Basic Vertebrate Fauna Survey and Risk Assessment
Menzies Mining Project





PINPOINT CARTOGRAPHICS (08) 9562 7136 2021-0125-f01.mxd


TERRESTRIAL ECOSYSTEMS

Kingwest Resources Limited
BASIC VERTEBRATE FAUNA SURVEY AND RISK ASSESSMENT
MENZIES MINING PROJECT

Figure 1

REGIONAL LOCATION

Drawn: S. Thompson | Date: 22 Mar 2022 | Job: 2021-0125



PINPOINT CARTOGRAPHICS (08) 9562 7136 2021-0125-f02.mxd

TERRESTRIAL ECOSYSTEMS

Kingwest Resources Limited
BASIC VERTEBRATE FAUNA SURVEY AND RISK ASSESSMENT
MENZIES MINING PROJECT

FAUNA HABITAT TYPES AND ASSESSMENT LOCATIONS

Figure 2

Drawn: S. Thompson | Date: 22 Mar 2022 | Job: 2021-0125

Appendix A. Results of the EPBC Act Protected Matters search

Basic Vertebrate Fauna Survey and Risk Assessment
Menzies Mining Project



Australian Government
Department of Agriculture, Water and the Environment

EPBC Act Protected Matters Report

This report provides general guidance on matters of national environmental significance and other matters protected by the EPBC Act in the area you have selected. Please see the caveat for interpretation of information provided here.

Report created: 28-Feb-2022

Summary
Details
- Matters of NES
- Other Matters Protected by the EPBC Act
- Extra Information

Caveat
Acknowledgements

Summary

Matters of National Environment Significance

This part of the report summarises the matters of national environmental significance that may occur in, or may relate to, the area you nominated. Further information is available in the detail part of the report, which can be accessed by scrolling or following the links below. If you are proposing to undertake an activity that may have a significant impact on one or more matters of national environmental significance then you should consider the Administrative Guidelines on Significance.

World Heritage Properties:	None
National Heritage Places:	None
Wetlands of International Importance (Ramsar	None
Great Barrier Reef Marine Park:	None
Commonwealth Marine Area:	None
Listed Threatened Ecological Communities:	None
Listed Threatened Species:	10
Listed Migratory Species:	9

Other Matters Protected by the EPBC Act

This part of the report summarises other matters protected under the Act that may relate to the area you nominated. Approval may be required for a proposed activity that significantly affects the environment on Commonwealth land, when the action is outside the Commonwealth land, or the environment anywhere when the action is taken on Commonwealth land. Approval may also be required for the Commonwealth or Commonwealth agencies proposing to take an action that is likely to have a significant impact on the

The EPBC Act protects the environment on Commonwealth land, the environment from the actions taken on Commonwealth land, and the environment from actions taken by Commonwealth agencies. As heritage values of a place are part of the 'environment', these aspects of the EPBC Act protect the Commonwealth Heritage values of a Commonwealth Heritage place. Information on the new heritage laws can be found at http://www.environment.gov.au/heritage

A permit may be required for activities in or on a Commonwealth area that may affect a member of a listed threatened species or ecological community, a member of a listed migratory species, whales and other cetaceans, or a member of a listed marine species.

Commonwealth Lands:	13
Commonwealth Heritage Places:	None
Listed Marine Species:	13
Whales and Other Cetaceans:	None
Critical Habitats:	None
Commonwealth Reserves Terrestrial:	None
Australian Marine Parks:	None
Habitat Critical to the Survival of Marine Turtles:	None

Extra Information

This part of the report provides information that may also be relevant to the area you have

State and Territory Reserves:	6
Regional Forest Agreements:	None
Nationally Important Wetlands:	3
EPBC Act Referrals:	7
Key Ecological Features (Marine):	None
Biologically Important Areas:	None
Bioregional Assessments:	None
Geological and Bioregional Assessments:	None

Details

Matters of National Environmental Significance

Listed Threatened Species		[Resource Information]
Status of Conservation Dependent and Extinct are not MNES under the EPBC Act. Number is the current name ID.		
Scientific Name	Threatened Category	Presence Text
BIRD		
Calidris ferruginea Curlew Sandpiper [856]	Critically Endangered	Species or species habitat likely to occur within area
Falco hypoleucos Grey Falcon [929]	Vulnerable	Species or species habitat may occur within area
Leipoa ocellata Malleefowl [934]	Vulnerable	Species or species habitat known to occur within area
Pezoporus occidentalis Night Parrot [59350]	Endangered	Species or species habitat may occur within area
Polytelis alexandrae Princess Parrot, Alexandra's Parrot [758]	Vulnerable	Species or species habitat known to occur within area
MAMMAL		
Dasyurus geoffroii Chuditch, Western Quoll [330]	Vulnerable	Species or species habitat known to occur within area
Sminthopsis psammophila Sandhill Dunnart [291]	Endangered	Species or species habitat likely to occur within area
PLANT		

Scientific Name	Threatened Category	Presence Text
Eleocharis papillosa Dwarf Desert Spike-rush [2519]	Vulnerable	Species or species habitat known to occur within area
Ricinocarpos brevis [82879]	Endangered	Species or species habitat may occur within area
Tecticornia flabelliformis Bead Glasswort [82664]	Vulnerable	Species or species habitat may occur within area

Listed Migratory Species

[Resource Information]

Scientific Name	Threatened Category	Presence Text
Migratory Marine Birds		
Apus pacificus Fork-tailed Swift [678]		Species or species habitat likely to occur within area
Migratory Terrestrial Species		
Motacilla cinerea Grey Wagtail [642]		Species or species habitat may occur within area
Motacilla flava Yellow Wagtail [644]		Species or species habitat may occur within area
Migratory Wetlands Species		
Actitis hypoleucos Common Sandpiper [59309]		Species or species habitat known to occur within area
Calidris acuminata Sharp-tailed Sandpiper [874]		Species or species habitat likely to occur within area
Calidris ferruginea Curlew Sandpiper [856]	Critically Endangered	Species or species habitat likely to occur within area
Calidris melanotos Pectoral Sandpiper [858]		Species or species habitat may occur within area

Scientific Name	Threatened Category	Presence Text
Charadrius veredus		
Oriental Plover, Oriental Dotterel [882]		Species or species habitat may occur within area
Tringa nebularia		
Common Greenshank, Greenshank [832]		Species or species habitat likely to occur within area

Other Matters Protected by the EPBC Act

Commonwealth Lands [Resource Information]

The Commonwealth area listed below may indicate the presence of Commonwealth land in this vicinity. Due to the unreliability of the data source, all proposals should be checked as to whether it impacts on a Commonwealth area, before making a definitive decision. Contact the State or Territory government land department for further information.

Commonwealth Land Name	State
Unknown	
Commonwealth Land - [51796]	WA
Commonwealth Land - [52197]	WA
Commonwealth Land - [51756]	WA
Commonwealth Land - [51754]	WA
Commonwealth Land - [51755]	WA
Commonwealth Land - [51752]	WA
Commonwealth Land - [51753]	WA
Commonwealth Land - [51058]	WA
Commonwealth Land - [52213]	WA
Commonwealth Land - [52232]	WA
Commonwealth Land - [51984]	WA
Commonwealth Land - [51751]	WA
Commonwealth Land - [51750]	WA

Listed Marine Species [Resource Information]

Scientific Name	Threatened Category	Presence Text
Bird		

Scientific Name	Threatened Category	Presence Text
Actitis hypoleucos Common Sandpiper [59309]		Species or species habitat known to occur within area
Apus pacificus Fork-tailed Swift [678]		Species or species habitat likely to occur within area overfly marine area
Bubulcus ibis as Ardea ibis Cattle Egret [66521]		Species or species habitat may occur within area overfly marine area
Calidris acuminata Sharp-tailed Sandpiper [874]		Species or species habitat likely to occur within area
Calidris ferruginea Curlew Sandpiper [856]	Critically Endangered	Species or species habitat likely to occur within area overfly marine area
Calidris melanotos Pectoral Sandpiper [858]		Species or species habitat may occur within area overfly marine area
Chalcites osculans as Chrysococcyx osculans Black-eared Cuckoo [83425]		Species or species habitat known to occur within area overfly marine area
Charadrius veredus Oriental Plover, Oriental Dotterel [882]		Species or species habitat may occur within area overfly marine area
Merops ornatus Rainbow Bee-eater [670]		Species or species habitat may occur within area overfly marine area
Motacilla cinerea Grey Wagtail [642]		Species or species habitat may occur within area overfly marine area

Scientific Name	Threatened Category	Presence Text
Motacilla flava		
Yellow Wagtail [644]		Species or species habitat may occur within area overfly marine area
Thinornis cucullatus as Thinornis rubricollis		
Hooded Dotterel, Hooded Plover [87735]		Species or species habitat known to occur within area overfly marine area
Tringa nebularia		
Common Greenshank, Greenshank [832]		Species or species habitat likely to occur within area overfly marine area

Extra Information

State and Territory Reserves [Resource Information]

Protected Area Name	Reserve Type	State
Bullock Holes Timber Reserve	5(1)(g) Reserve	WA
Clear And Muddy Lakes	Nature Reserve	WA
Credo	NRS Addition - Gazettal in Progress	WA
Goongarrie	National Park	WA
Rowles Lagoon	Conservation Park	WA
Unnamed WA46847	Nature Reserve	WA

Nationally Important Wetlands [Resource Information]

Wetland Name	State
Lake Ballard	WA
Lake Marmion	WA
Rowles Lagoon System	WA

EPBC Act Referrals [Resource Information]

Title of referral	Reference	Referral Outcome	Assessment Status
Controlled action			
Northern Star Resources - Carosue Dam TSF Cell 4	2021/9026	Controlled Action	Assessment Approach
Not controlled action			

Title of referral	Reference	Referral Outcome	Assessment Status
Not controlled action			
Construction of a bypass road, haulage contractor workshop & laydown yard	2012/6639	Not Controlled Action	Completed
Eastern Goldfields Gas Pipeline Construction, WA	2014/7284	Not Controlled Action	Completed
Improving rabbit biocontrol: releasing another strain of RHDV, sthrn two thirds of Australia	2015/7522	Not Controlled Action	Completed
Murrin Murrin East Nickel and Cobalt Mine Expansion	2008/4140	Not Controlled Action	Completed
Saracen Gold-Carosue Dam Aerodrome, WA	2017/7925	Not Controlled Action	Completed
Ularring Hematite Project, WA	2012/6426	Not Controlled Action	Completed

Caveat

1 PURPOSE

This report is designed to assist in identifying the location of matters of national environmental significance (MNES) and other matters protected by the Environment Protection and Biodiversity Conservation Act 1999 (Cth) (EPBC Act) which may be relevant in determining obligations and requirements under the EPBC Act.

The report contains the mapped locations of:

- World and National Heritage properties;
- Wetlands of International and National Importance;
- Commonwealth and State/Territory reserves;
- distribution of listed threatened, migratory and marine species;
- listed threatened ecological communities; and
- other information that may be useful as an indicator of potential habitat value.

2 DISCLAIMER

This report is not intended to be exhaustive and should only be relied upon as a general guide as mapped data is not available for all species or ecological communities listed under the EPBC Act (see below). Persons seeking to use the information contained in this report to inform the referral of a proposed action under the EPBC Act should consider the limitations noted below and whether additional information is required to determine the existence and location of MNES and other protected matters.

Where data are available to inform the mapping of protected species, the presence type (e.g. known, likely or may occur) that can be determined from the data is indicated in general terms. It is the responsibility of any person using or relying on the information in this report to ensure that it is suitable for the circumstances of any proposed use. The Commonwealth cannot accept responsibility for the consequences of any use of the report or any part thereof. To the maximum extent allowed under governing law, the Commonwealth will not be liable for any loss or damage that may be occasioned directly or indirectly through the use of, or reliance

3 DATA SOURCES

Threatened ecological communities

For threatened ecological communities where the distribution is well known, maps are generated based on information contained in recovery plans, State vegetation maps and remote sensing imagery and other sources. Where threatened ecological community distributions are less well known, existing vegetation maps and point location data are used to produce indicative distribution maps.

Threatened, migratory and marine species

Threatened, migratory and marine species distributions have been discerned through a variety of methods. Where distributions are well known and if time permits, distributions are inferred from either thematic spatial data (i.e. vegetation, soils, geology, elevation, aspect, terrain, etc.) together with point locations and described habitat; or modelled (MAXENT or BIOCLIM habitat modelling) using

Where little information is available for a species or large number of maps are required in a short time-frame, maps are derived either from 0.04 or 0.02 decimal degree cells; by an automated process using polygon capture techniques (static two kilometre grid cells, alpha-hull and convex hull); or captured manually or by using topographic features (national park boundaries, islands, etc.).

In the early stages of the distribution mapping process (1999-early 2000s) distributions were defined by degree blocks, 100K or 250K map sheets to rapidly create distribution maps. More detailed distribution mapping methods are used to update these distributions

4 LIMITATIONS

The following species and ecological communities have not been mapped and do not appear in this report:

- threatened species listed as extinct or considered vagrants;
- some recently listed species and ecological communities;
- some listed migratory and listed marine species, which are not listed as threatened species; and
- migratory species that are very widespread, vagrant, or only occur in Australia in small numbers.

The following groups have been mapped, but may not cover the complete distribution of the species:

- listed migratory and/or listed marine seabirds, which are not listed as threatened, have only been mapped for recorded
- seals which have only been mapped for breeding sites near the Australian continent

The breeding sites may be important for the protection of the Commonwealth Marine environment.

Refer to the metadata for the feature group (using the Resource Information link) for the currency of the information.

Acknowledgements

This database has been compiled from a range of data sources. The department acknowledges the following custodians who have contributed valuable data and advice:

-Office of Environment and Heritage, New South Wales
-Department of Environment and Primary Industries, Victoria
-Department of Primary Industries, Parks, Water and Environment, Tasmania
-Department of Environment, Water and Natural Resources, South Australia
-Department of Land and Resource Management, Northern Territory
-Department of Environmental and Heritage Protection, Queensland
-Department of Parks and Wildlife, Western Australia
-Environment and Planning Directorate, ACT
-Birdlife Australia
-Australian Bird and Bat Banding Scheme
-Australian National Wildlife Collection
-Natural history museums of Australia
-Museum Victoria
-Australian Museum
-South Australian Museum
-Queensland Museum
-Online Zoological Collections of Australian Museums
-Queensland Herbarium
-National Herbarium of NSW
-Royal Botanic Gardens and National Herbarium of Victoria
-Tasmanian Herbarium
-State Herbarium of South Australia
-Northern Territory Herbarium
-Western Australian Herbarium
-Australian National Herbarium, Canberra
-University of New England
-Ocean Biogeographic Information System
-Australian Government, Department of Defence
Forestry Corporation, NSW
-Geoscience Australia
-CSIRO
-Australian Tropical Herbarium, Cairns
-eBird Australia
-Australian Government – Australian Antarctic Data Centre
-Museum and Art Gallery of the Northern Territory
-Australian Government National Environmental Science Program
-Australian Institute of Marine Science
-Reef Life Survey Australia
-American Museum of Natural History
-Queen Victoria Museum and Art Gallery, Inveresk, Tasmania
-Tasmanian Museum and Art Gallery, Hobart, Tasmania
-Other groups and individuals

The Department is extremely grateful to the many organisations and individuals who provided expert advice and information on numerous draft distributions.

Please feel free to provide feedback via the Contact Us page.

© Commonwealth of Australia

Department of Agriculture Water and the Environment
GPO Box 858
Canberra City ACT 2601 Australia
+61 2 6274 1111

Appendix B. Vertebrate fauna recorded in biological surveys in the region

Basic Vertebrate Fauna Survey and Risk Assessment
Menzies Mining Project



B.1 VERTEBRATE FAUNA ASSESSMENTS

		Surveys	A	B										C													D						E	F
Family	Species	Common name		GG26	GG27	GG29	GG28	GS28	GS29	GS26	GS27	GS30	GG30	Spinifex	Salmon Gums	Gimlet South	Davyhurst	Gimlet South	Security	Crossroads	Gimlet South	Wendy Gully	Wendy Gully	Wendy Gully	Floodplains	MME1	MME2	Opportunistic	MME3	MME7	MME6	Goondarrie	Jump Up Dam
Amphibians																																			
Limnodynastidae	*Neobatrachus kunapalari*	Wheatbelt Frog	X											1																					
	Neobatrachus sudelli	Sudell's Frog	X																																
	Neobatrachus sutor	Shoemaker Frog	X											9	3	6	10	30	22	12	7					1	1								
	Neobatrachus wilsmorei	Plonking Frog	X		3	2																													
	Platyplectrum spenceri	Spencer's Burrowing Frog	X																																
Myobatrachidae	*Crinia georgiana*	Quacking Frog	X																																
	Pseudophryne occidentalis	Western Toadlet	X												1	147	1	84		4	158	2													
Pelodryadidae	*Cyclorana maini*	Main's Frog	X																									1							
	Cyclorana occidentalis	Western Water-holding Frog	X																																
	Litoria moorei	Motorbike Frog	X																																
Reptiles																																			
Agamidae	*Ctenophorus cristatus*	Crested Dragon	X				5	1	1					1	1		3	5	1	1			1													
	Ctenophorus fordi	Mallee Dragon	X	22	42	2	15	2	2	6	9																									
	Ctenophorus infans	Ring-tailed Dragon	X																																
	Ctenophorus isolepis	Central Military Dragon																								1									
	Ctenophorus nuchalis	Central Netted Dragon	X																																
	Ctenophorus ornatus	Ornate Crevice Dragon	X																																
	Ctenophorus pictus	Painted Dragon	X																																
	Ctenophorus reticulatus	Western Netted Dragon	X									1	2		3	1	4	13	30	6		1	1	3			1	1	1	3			1	
	Ctenophorus salinarum	Saltpan Dragon	X																																
	Ctenophorus scutulatus	Lozenge-marked Dragon	X		3	7	3		8			3	1				2	2	5				1	13											
	Diporiphora amphiboluroides	Mulga Dragon	X																7																1
	Moloch horridus	Thorny Devil	X		1				1	1	2		1				5					1	1	17											
	Pogona minor	Western Bearded Dragon	X	1	1	1	1		3	1	1		3	13	2	4	11	3	14	21	12	14	4	24	2										
	Tympanocryptis cephalus	Pebble Dragon	X													1		7			2			1											
Carphodactylidae	*Nephrurus laevissimus*	Smooth Knob-tail	X	18	18		2	1	1	12	9																								
	Nephrurus vertebralis	Midline Knob-tail	X																																

		Surveys	A	B										C												D						E	F
Family	Species	Common name		GG26	GG27	GG29	GG28	GS28	GS29	GS26	GS27	GS30	GG30	Spinifex	Salmon Gums	Gimlet South	Davyhurst	Gimlet South	Security	Crossroads	Gimlet South	Wendy Gully	Wendy Gully	Wendy Gully	Floodplains	MME1	MME2	Opportunistic	MME3	MME7	MME6	Goonaarrie	Jump Up Dam
	Nephrurus wheeleri	Banded Knob-tail	X																														
	Underwoodisaurus milii	Barking Gecko	X								9			11	31	231	16	18		2	83	37	33	28	10						2		1
Diplodactylidae	*Amalosia reticulata*	Reticulated Velvet Gecko															1																
	Diplodactylus conspicillatus	Fat-tailed Gecko	X																														
	Diplodactylus granariensis	Wheatbelt Stone Gecko	X			2	1	5	8	4	8	4		77	18	8	74	71	8	29	22	33	38	76	1									
	Diplodactylus pulcher	Beautiful Gecko	X						1			2	1	53	8	1	86	21	123	80		1	3	46	12						1			
	Lucasium maini	Main's Ground Gecko	X			1	2	2						9	346		9	60	1	9	2		1	1	1									
	Lucasium squarrosum	Mottled Ground Gecko	X																														
	Rhynchoedura ornata	Beaked Gecko	X		2	1	2	2	3	1				4	3		5			41				9										1
	Strophurus assimilis	Goldfields Spiny-tailed Gecko	X							3				44	1	3	1	7			3	14	15	112										
	Strophurus elderi	Jewelled Gecko	X																														
	Strophurus intermedius	Southern Spiny-tailed Gecko																															
	Strophurus strophurus	Western Spiny-tailed Gecko	X																														
	Strophurus wellingtonae	Western Shield Spiny-tailed Gecko	X																								1						
Elapidae	*Brachyurophis fasciolatus*	Narrow-banded Burrowing Snake									1																						
	Brachyurophis semifasciata	Half-girdled Snake	X							1		1		9	7		6	6	1														1
	Demansia psammophis	Yellow-faced Whipsnake	X				2							1	1		1	4	1					3										
	Elapognathus coronatus	Crowned Snake	X																														
	Furina ornata	Orange-naped Snake	X																														
	Neelaps bimaculatus	Black-naped Burrowing Snake	X																														
	Notechis scutatus	Tiger Snake	X																														
	Suta monachus	Hooded Snake	X				1							2	7		9	4	4	2			1	6				1					
	Pseudechis australis	Mulga Snake	X												1		2		1		1	1											
	Pseudechis butleri	Spotted Mulga Snake	X																								1						
	Pseudonaja mengdeni	Western Brown Snake	X											1									1	1									
	Pseudonaja modesta	Ringed Brown Snake	X		1		3							1			1							1									
	Simoselaps bertholdi	Jan's Banded Snake	X						1						4		8	2		1				2									
	Suta fasciata	Rosen's Snake	X												2			3	1				1										
Gekkonidae	*Christinus marmoratus*	Marbled Gecko	X																														

		Surveys	A	B										C													D						E	F
Family	Species	Common name		GG26	GG27	GG29	GG28	GS28	GS29	GS26	GS27	GS30	GG30	Spinifex	Salmon Gums	Gimlet South	Davvhurst	Gimlet South	Security	Crossroads	Gimlet South	Wendy Gully	Wendy Gully	Wendy Gully	Floodplains	MME1	MME2	Opportunistic	MME3	MME7	MME6	Goonaarrie	Jump Up Dam
	Gehyra punctata	Spotted Dtella	X																															
	Gehyra purpurascens	Purplish Dtella	X				2							1	1		1	1		6															
	Gehyra variegata	Variegated Gehyra	X	1	1		3	4	6		2	3	1	23	14	27	38	37	39	6	18	3	1	12	2	3	9	1	3	2	9		1
	Heteronotia binoei	Bynoe's Gecko	X										2	24	10	21	16	9	25	1	29	42	27	8			3	1					1
Pygopodidae	*Aprasia picturata*	Black-headed Worm-lizard	X																															
	Delma australis	Marble-faced Delma	X											8			4	3						6										
	Delma butleri	Unbanded Delma	X	1			1							4						2				2										
	Delma fraseri	Fraser's Delma												1						1														
	Delma nasuta	Sharp-snouted Delma																																
	Lialis burtonis	Burton's Legless Lizard	X											5										3										
	Pygopus lepidopodus	Common Scaly-foot												2	3		2	2						1										
	Pygopus nigriceps	Western Hooded Scaly-foot	X			1																												
Pythonidae	*Antaresia stimsoni*	Stimson's Python	X																															
Scincidae	*Cryptoblepharus australis*	Inland Snake-eyed Skink	X																															
	Cryptoblepharus buchananii	Buchanan's Snake-eyed Skink	X			1	3				1		3		3		10	12	3							2	1							
	Cryptoblepharus plagiocephalus	Peron's Snake-eyed Skink	X																															
	Ctenotus atlas	Southern Mallee Ctenotus	X	4	3	1	4	3	2	2	3			16					1				2	104										
	Ctenotus brooksi	Wedgsnout Ctenotus	X	17						3																								
	Ctenotus brooksi	Wedgsnout Ctenotus	X																															
	Ctenotus leae	Orange-tailed Finesnout Ctenotus	X																															
	Ctenotus leonhardii	Leonhardi's Ctenotus	X																									1						
	Ctenotus pantherinus	Leopard Ctenotus	X																															
	Ctenotus schomburgkii	Barred Wedgesnout Ctenotus	X	4	9	3	5	5	1		1			2										2		1		1						
	Ctenotus severus	Stern Ctenotus	X																															
	Ctenotus uber	Spotted Ctenotus	X			1						1	6	46	6		29	13	44	27		2	1	25										
	Ctenotus xenopleura	Wide-striped Ctenotus	X																															
	Cyclodomorphus melanops	Spinifex Slender Blue-tongue	X			10	2		2			2		24		1	1	2				2	2	24										
	Egernia depressa	Southern Pygmy Spiny-tailed Skink	X											15		3	57	68	27		3										1		1
	Egernia formosa	Goldfields Crevice Skink	X										5	1	4		8		8	1													1

		Surveys	A	B										C													D						E	F
Family	Species	Common name		GG26	GG27	GG29	GG28	GS28	GS29	GS26	GS27	GS30	GG30	Spinifex	Salmon Gums	Gimlet South	Davvhurst	Gimlet South	Security	Crossroads	Gimlet South	Wendy Gully	Wendy Gully	Wendy Gully	Floodplains	MME1	MME2	Opportunistic	MME3	MME7	MME6	Goonaarrie	Jump Up Dam
	Egernia napoleonis	Southwestern Crevice Skink	X																															
	Eremiascincus richardsonii	Broad-banded Sand-swimmer	X											3	6	2	5	4	6	2	1	1		1										
	Hemiergis initialis	South-western Earless Skink	X											12	1		4	5			1													
	Lerista desertorum	Central Desert Robust Slider	X																									1			1			
	Lerista kingi	King's Slider	X																															
	Lerista macropisthopus	Unpatterned Robust Slider	X				1			2																								
	Lerista muelleri	Wood Mulch-slider	X																															
	Lerista picturata	Southern Robust Slider												14	20		18	18		1				20										
	Lerista picturata	Southern Robust Slider	X																															
	Lerista timida	Timid Slider	X																															
	Liopholis inornata	Desert Skink	X	3	2	1		2		2	4				4				2					2										
	Liopholis striata	Nocturnal Desert Skink	X												2				9					1										
	Menetia greyii	Common Dwarf Skink	X	1	2	1	1	1	1		1		1	6	3		19	3	17	4	2			1		4		1						
	Morethia adelaidensis	Saltbush Morethia Skink	X																															
	Morethia butleri	Woodland Morethia Skink	X										2	4	7	3	14	1	4				1				2	1		1	3			
	Saiphos equalis	Three-toed Skink	X																															
	Tiliqua occipitalis	Western Blue-tongued Lizard	X		1						1			5			1		3					4										
	Tiliqua rugosa	Bobtail	X											2			3	1	2	1				1	1									
Typhlopidae	*Anilios australis*	Austral Blind Snake	X						2	1				14	7		8	14		7	1		1	6										
	Anilios bicolor	Dark-spined Blind Snake												1				1						1										
	Anilios bituberculatus	Prong-snouted Blind Snake						1						1			2	2	1		1		1											
	Anilios hamatus	Pale-headed Blind Snake							1					9	10	2	10	24	2	13		1	1	9										
Varanidae	*Varanus caudolineatus*	Stripe-tailed Monitor	X											1	11		11	15	17	9				9			1				1			
	Varanus giganteus	Perentie	X																															
	Varanus gouldii	Gould's Goanna	X			2		1						6	8	1	10	9	2	2	1	2	1		1									
	Varanus panoptes	Yellow-spotted Monitor																										1			1			1
	Varanus tristis	Black-headed Monitor	X									1		3	3		5	1																
Birds																																		
Casuariidae	*Dromaius novaehollandiae*	Emu																								1	1	1			1			1
Anatidae	*Cygnus atratus*	Black Swan																										1						
	Tadorna tadornoides	Australian Shelduck																										1						

		Surveys	A	B										C												D						E	F
Family	Species	Common name		GG26	GG27	GG29	GG28	GS28	GS29	GS26	GS27	GS30	GG30	Spinifex	Salmon Gums	Gimlet South	Davvhurst	Gimlet South	Security	Crossroads	Gimlet South	Wendy Gully	Wendy Gully	Wendy Gully	Floodplains	MME1	MME2	Opportunistic	MME3	MME7	MME6	Goonaarrie	Jump Up Dam
	Anas superciliosa	Pacific Black Duck																								1							
	Anas gracilis	Grey Teal																								1							
	Malacorhynchus membranaceus	Pink-eared Duck																								1							
Megapodiidae	*Leipoa ocellata*	Malleefowl																								1							1
Columbidae	*Phaps chalcoptera*	Common Bronzewing																								1							1
	Ocyphaps lophotes	Crested Pigeon																							2	1				2			1
Cuculidae	*Chrysococcyx basalis*	Horsfield's Bronze-Cuckoo																															1
	Chrysococcyx osculans	Black-eared Cuckoo																															1
Aegothelidae	*Aegotheles cristatus*	Australian Owlet-nightjar																															1
Caprimulgidae	*Eurostopodus argus*	Spotted Nightjar																															1
Apodidae	*Apus pacificus*	Pacific Swift																															1
Rallidae	*Tribonyx ventralis*	Black-tailed Nativehen																								1							
Recurvirostridae	*Himantopus leucocephalus*	Pied Stilt																								1							
	Recurvirostra novaehollandiae	Red-necked Avocet																								1							
Charadriidae	*Charadrius ruficapillus*	Red-capped Plover																								1							
Charadriidae	*Elseyornis melanops*	Black-fronted Dotterel																								1							
Turnicidae	*Turnix velox*	Little Buttonquail																															1
Otididae	*Ardeotis australis*	Australian Bustard																															1
Ardeidae	*Ardea pacifica*	White-necked Heron																								1							
	Egretta novaehollandiae	White-faced Heron																								1							
Accipitridae	*Haliaeetus albicilla*																								1		1	2		1			
	Hieraaetus morphnoides	Little Eagle																									1							
	Accipiter cirrocephalus	Collared Sparrowhawk																															1
Cuculidae	*Heteroscenes pallidus*	Pallid Cuckoo																								1							
Alcedinidae	*Dacelo novaeguineae*	Laughing Kookaburra																														1	
Meropidae	*Merops ornatus*	Rainbow Bee-eater																															1
Falconidae	*Falco longipennis*	Australian Hobby																										1					1
	Falco berigora	Brown Falcon																															1
	Falco peregrinus	Peregrine Falcon																									1						
Cacatuidae	*Eolophus roseicapilla*	Galah																								1							1
	Nymphicus hollandicus	Cockatiel																															1

		Surveys	A	B										C												D						E	F
Family	Species	Common name		GG26	GG27	GG29	GG28	GS28	GS29	GS26	GS27	GS30	GG30	Spinifex	Salmon Gums	Gimlet South	Davvhurst	Gimlet South	Security	Crossroads	Gimlet South	Wendy Gully	Wendy Gully	Wendy Gully	Floodplains	MME1	MME2	Opportunistic	MME3	MME7	MME6	Goonaarrie	Jump Up Dam
Psittacidae	*Neopsephotus bourkii*	Bourke's Parrot																									1						1
	Barnardius zonarius	Australian Ringneck																									1	1		2	3	1	1
	Psephotus varius	Mulga Parrot																										1	1	5	5		1
	Melopsittacus undulatus	Budgerigar																															1
Ptilonorhynchidae	*Chlamydera guttata*	Western Bowerbird	X																														1
Climacteridae	*Climacteris affinis*	White-browed Treecreeper	X																									1		2			1
	Climacteris rufus	Rufous Treecreeper	X																														
Maluridae	*Malurus pulcherrimus*	Blue-breasted Fairywren	X																														
	Malurus splendens	Splendid Fairywren	X																									1		9		1	1
	Malurus leucopterus	White-winged Fairywren	X																							3							1
Meliphagidae	*Certhionyx variegatus*	Pied Honeyeater	X																														
	Purnella albifrons	White-fronted Honeyeater	X																							80	100	1	12	10	1		1
	Manorina flavigula	Yellow-throated Miner	X																							10	5	1	7		10	1	1
	Acanthagenys rufogularis	Spiny-cheeked Honeyeater	X																							25	20	1		1	2	1	1
	Anthochaera carunculata	Red Wattlebird	X																													1	1
	Gavicalis virescens	Singing Honeyeater	X																								4	1	2	1	1	1	1
	Ptilotula ornata	Yellow-plumed Honeyeater	X																														
	Epthianura tricolor	Crimson Chat	X																														1
	Epthianura aurifrons	Orange Chat	X																														
	Epthianura albifrons	White-fronted Chat	X																														
	Sugomel nigrum	Black Honeyeater	X																														
	Lichmera indistincta	Brown Honeyeater	X																														1
	Nesoptilotis leucotis	White-eared Honeyeater	X																													1	
	Melithreptus brevirostris	Brown-headed Honeyeater	X																													1	
Pardalotidae	*Pardalotus punctatus*	Spotted Pardalote	X																														
	Pardalotus striatus	Striated Pardalote	X																									1				1	1
Acanthizidae	*Pyrrholaemus brunneus*	Redthroat	X																									1				1	1
	Calamanthus campestris	Rufous Fieldwren																															
	Acanthiza iredalei	Slender-billed Thornbill	X																													1	
	Acanthiza apicalis	Inland Thornbill	X																							2		1		6	2	1	1
	Acanthiza chrysorrhoa	Yellow-rumped Thornbill	X																							5	6	1		4	2		1

		Surveys	A	B										C												D						E	F
Family	Species	Common name		GG26	GG27	GG29	GG28	GS28	GS29	GS26	GS27	GS30	GG30	Spinifex	Salmon Gums	Gimlet South	Davvhurst	Gimlet South	Security	Crossroads	Gimlet South	Wendy Gully	Wendy Gully	Wendy Gully	Floodplains	MME1	MME2	Opportunistic	MME3	MME7	MME6	Goonaarrie	Jump Up Dam
	Acanthiza uropygialis	Chestnut-rumped Thornbill	X																							8	30	1	2	50	15	1	1
	Acanthiza robustirostris	Slaty-backed Thornbill	X																									1		2			
	Smicrornis brevirostris	Weebill	X																									1					1
	Gerygone fusca	Western Gerygone	X																														
	Aphelocephala leucopsis	Southern Whiteface	X																									1		20	6		1
Pomatostomidae	*Pomatostomus superciliosus*	White-browed Babbler	X																									1				1	1
Cinclosomatidae	*Cinclosoma castanotum*	Chestnut Quail-thrush	X																														
	Cinclosoma castaneothorax	Chestnut-breasted Quail-thrush	X																													1	1
Campephagidae	*Coracina maxima*	Ground Cuckooshrike	X																														
	Coracina novaehollandiae	Black-faced Cuckooshrike	X																								2	1				1	1
	Lalage tricolor	White-winged Triller	X																														1
Neosittidae	*Daphoenositta chrysoptera*	Varied Sittella	X																													1	
Psophodidae	*Psophodes occidentalis*	Chiming Wedgebill	X																														
Oreoicidae	*Oreoica gutturalis*	Crested Bellbird	X																							1	3	1	1	2	1	1	1
Pachycephalidae	*Colluricincla harmonica*	Grey Shrikethrush	X																									1		2	1	1	1
	Pachycephala inornata	Gilbert's Whistler	X																														
	Pachycephala pectoralis	Golden Whistler	X																														
	Pachycephala rufiventris	Rufous Whistler	X																									1		1	1	1	1
Artamidae	*Artamus personatus*	Masked Woodswallow	X																														1
	Artamus superciliosus	White-browed Woodswallow																										1	4		1		
	Artamus cinereus	Black-faced Woodswallow	X																														
	Artamus cyanopterus	Dusky Woodswallow	X																														
	Artamus minor	Little Woodswallow	X																														
	Cracticus torquatus	Grey Butcherbird	X																							1	1	1	1	1	1	1	
	Cracticus nigrogularis	Pied Butcherbird	X																							2	1	1	1			1	1
	Gymnorhina tibicen	Australian Magpie	X																							3		1					1
	Strepera versicolor	Grey Currawong	X																										1			1	1
Rhipiduridae	*Rhipidura leucophrys*	Willie Wagtail	X																							1		1				1	1
	Rhipidura albiscapa	Grey Fantail	X																											1		1	
Monarchidae	*Grallina cyanoleuca*	Magpie-lark	X																								1	1	2		2		
Corvidae	*Corvus orru*	Torresian Crow	X																								1	1	2		1		

		Surveys	A	B										C													D						E	F
Family	Species	Common name		GG26	GG27	GG29	GG28	GS28	GS29	GS26	GS27	GS30	GG30	Spinifex	Salmon Gums	Gimlet South	Davvhurst	Gimlet South	Security	Crossroads	Gimlet South	Wendy Gully	Wendy Gully	Wendy Gully	Floodplains	MME1	MME2	Opportunistic	MME3	MME7	MME6	Goonaarrie	Jump Up Dam
	Corvus bennetti	Little Crow	X																							2	1		1		1	1
	Corvus coronoides	Australian Raven	X																														
Petroicidae	*Microeca fascinans*	Jacky Winter	X																														
	Petroica goodenovii	Red-capped Robin	X																						1	2	1		6	2	1	1
	Melanodryas cucullata	Hooded Robin	X																								1	3			1	
	Drymodes brunneopygia	Southern Scrub-Robin	X																														
Locustellidae	*Cincloramphus cruralis*	Brown Songlark	X																														
	Cincloramphus mathewsi	Rufous Songlark	X																														
Hirundinidae	*Hirundo rustica*	Barn Swallow																												5			
	Hirundo neoxena	Welcome Swallow	X																														
	Petrochelidon ariel	Fairy Martin	X																														
	Petrochelidon nigricans	Tree Martin	X																														
	Cheramoeca leucosterna	White-backed Swallow	X																								1	2					
Dicaeidae	*Dicaeum hirundinaceum*	Mistletoebird	X																												1	1	
Estrildidae	*Taeniopygia guttata*	Zebra Finch	X																								1						1
Motacillidae	*Anthus novaeseelandiae*	Australasian Pipit	X											1		1									4		1	4					1
Mammals																																		
Tachyglossidae	*Tachyglossus aculeatus*	Short-beaked Echidna	X																							1	1						1
Bovidae	*Bos taurus*	Cow																															1
	Capra hircus	Goat																									1						1
Camelidae	*Camelus dromedarius*	Dromedary	X																														
Suidae	*Sus scrofa*	Pig	X																														
Canidae	*Canis lupus*	Dingo	X																								1						
	Vulpes vulpes	Red Fox																									1						1
Felidae	*Felis catus*	Cat																															1
Molossidae	*Austronomus australis*	White-striped Freetail Bat	X																														
	Mormopterus planiceps	Southern Free-tail Bat	X																														
	Mormopterus sp. 4	South-western Free-tail Bat																															1
Vespertilionidae	*Nyctophilus* sp.	Long-eared Bat Sp.																															1
	Chalinolobus gouldii	Gould's Wattled Bat	X																														1
	Chalinolobus morio	Chocolate Wattled Bat																															1

		Surveys	A	B										C												D						E	F
Family	Species	Common name		GG26	GG27	GG29	GG28	GS28	GS29	GS26	GS27	GS30	GG30	Spinifex	Salmon Gums	Gimlet South	Davyhurst	Gimlet South	Security	Crossroads	Gimlet South	Wendy Gully	Wendy Gully	Wendy Gully	Floodplains	MME1	MME2	Opportunistic	MME3	MME7	MME6	Goonaarrie	Jump Up Dam
	Nyctophilus geoffroyi	Lesser Long-eared Bat	X																														
	Nyctophilus major	Greater Long-eared Bat	X												1																		
	Scotorepens balstoni	Inland Broad-nosed Bat	X																														1
	Vespadelus baverstocki	Inland Forest Bat	X																														
	Vespadelus regulus	Southern Forest Bat	X																														
Dasyuridae	*Ningaui sp.*	Ningaui sp.												35	2		2					2	17										
	Antechinomys laniger	Kultarr	X												1						1												
	Ningaui ridei	Wongai Ningaui	X	1				4	3	5				1									2										
	Ningaui yvonneae	Mallee Ningaui	X											1																			
	Pseudantechinus woolleyae	Woolley's False Antechinus	X																					1									
	Sminthopsis crassicaudata	Fat-tailed Dunnart	X	1					1					2	5	14		2	4	26	32	121	100	24	108	1			1					
	Sminthopsis dolichura	Little Long-tailed Dunnart	X	1	1	1	1		1	2	2	12		63	34	4	47	15	46	11	2	7	4	32	2								
	Sminthopsis gilberti	Gilbert's Dunnart	X																														
	Sminthopsis hirtipes	Hairy-footed Dunnart	X																														
	Sminthopsis longicaudata	Long-tailed Dunnart																															
	Sminthopsis ooldea	Ooldea Dunnart	X																														
Burramyidae	*Cercartetus concinnus*	Southwestern Pygmy Possum	X											23	15	23	37	62	8	17	27	9	6	16									
Macropodidae	*Macropus fuliginosus*	Western Grey Kangaroo	X																									1					
	Osphranter robustus	Euro	X																									1					1
	Osphranter rufus	Red Kangaroo	X																									1	5				1
Phalangeridae	*Trichosurus vulpecula*	Common Brushtail Possum	X																														
Leporidae	*Oryctolagus cuniculus*	Rabbit																1	1									1					1
Equidae	*Equus asinus*	Donkey																										1					
Muridae	*Mus musculus*	House Mouse	X					1		2	4			26	6	62	19	25	10	18	128	181	88	13	31	1	2		2		2		
	Notomys alexis	Spinifex Hopping Mouse	X	9	3	1	1		2																	7				2			
	Notomys mitchellii	Mitchell's Hopping Mouse	X	1													1				1												
	Pseudomys albocinereus	Ash-grey Mouse	X																			1											
	Pseudomys bolami	Bolam's Mouse	X											9	30	11	49	13	1	8	20			5	4								
	Pseudomys hermannsburgensis	Sandy Inland Mouse	X		2				4	1				8	9	3	9	5		2	5	2	1	5	2						1		
	Pseudomys nanus	Western Chestnut Mouse	X																														

A Atlas of Living Australia

B Cowan, M.A. and How, R.A. (2004) Comparisons of ground vertebrate assemblages in arid Western Australia in different seasons and decades, *Records of the Western Australian Museum*, 22, 91-100
C Thompson, S.A. (2004) *Mine site rehabilitation index using reptile assemblage as a bio-indicator*, PhD Thesis, Edith Cowan University, Perth plus additional data collected after the PhD project.
D Ninox Wildlife Consulting (1998) *A Vertebrate Fauna Survey of the Murrin Murrin Expansion Project*, Unpublished report for Anaconda Nickel Ltd, Perth.
E Bell, D.T., Bell, R.C. and Loneragan, W.A. (2007) Winter bird assemblages across an arid gradient in south-west Western Australia, *Journal of the Royal Society of Western Australia*, 90, 219-227.
F Ecologia Environment (2007) *Jump Up Dam Fauna Assessment*, Unpublished report for Heron Resources Limited, Perth.

B.2 VERTEBRATE FAUNA ASSESSMENTS

		Surveys	A															B									C						
Family	Species	Common name	Site 13	Site 3	Site 9	Site 9a	Site 12	Site 21	Site 22	Site 14	Site 15	Site 21a	Site 19	Freshwater	Goomgarri	Salt Lake	Site 12a	Site 3	Site 5	Site 7	Site 4	Site 1	Site 6	Site 8	Opportunisti	Site 2	Site 1	Site 2	Site 3	Site 4	Site 5	Site 6	Site 9
Amphibians																																		
Limnodynastidae	*Neobatrachus kunapalari*	Wheatbelt Frog																																
	Neobatrachus sutor	Shoemaker Frog	3	1	5	10																												
	Neobatrachus wilsmorei	Plonking Frog	1		11		2	2																										
Reptiles																																		
Agamidae	*Ctenophorus cristatus*	Crested Dragon							5																									
	Ctenophorus fordi	Mallee Dragon	43	26				2	16									7	11															
	Ctenophorus reticulatus	Western Netted Dragon			2	1				2	4	4								1														
	Ctenophorus scutulatus	Lozenge-marked Dragon																		15	3						1	3	5	3	1			
	Ctenophorus vadnappa	Red-barred Dragon	3		2	1		7	3		1	2																						
	Diporiphora amphiboluroides	Mulga Dragon																											2					
	Moloch horridus	Thorny Devil	1			1	2				1							1																
	Pogona minor	Western Bearded Dragon																				1	6					1		1				
	Pogona minor	Western Bearded Dragon	1	1	2		4	2	1	1	3	1	2																					
Carphodactylidae	*Nephrurus laevissimus*	Smooth Knob-tail	18	18			1		2										28															
	Underwoodisaurus milii	Barking Gecko																				1		1										
Diplodactylidae	*Amalosia reticulata*	Reticulated Velvet Gecko																1			2	1												
	Diplodactylus granariensis	Wheatbelt Stone Gecko					1	2	1			1						1	1	1	5	4		1										
	Diplodactylus pulcher	Beautiful Gecko									1		1							1		1	4					1			1			
	Lucasium maini	Main's Ground Gecko					3	1	2									6		1	6	1												
	Rhynchoedura ornata	Beaked Gecko	2		1		7	1	2																									
	Strophurus assimilis	Goldfields Spiny-tailed Gecko																5									1							
	Strophurus elderi	Jewelled Gecko																	1															
	Strophurus intermedius	Southern Spiny-tailed Gecko					2																											
Elapidae	*Brachyurophis semifasciata*	Half-girdled Snake																	1		1	1												
	Demansia psammophis	Yellow-faced Whipsnake																1					1	1										
	Demansia psammophis	Yellow-faced Whipsnake							2																									
	Suta monachus	Hooded Snake							1																									
	Pseudonaja mengdeni	Western Brown Snake					1														1													
	Pseudonaja modesta	Ringed Brown Snake	1						3																									

		Surveys	A															B								C						
Family	Species	Common name	Site 13	Site 3	Site 9	Site 9a	Site 12	Site 21	Site 22	Site 14	Site 15	Site 21a	Site 19	Freshwater	Goongarri	Salt Lake	Site 12a	Site 3	Site 5	Site 7	Site 4	Site 1	Site 6	Site 8	Opportunisti	Site 2	Site 1	Site 2	Site 3	Site 4	Site 5	Site 6	Site 9
	Simoselaps bertholdi	Jan's Banded Snake											1											1									
Gekkonidae	*Gehyra purpurascens*	Purplish Dtella							2													1		2									
	Gehyra variegata	Variegated Gehyra	1	1			2		4		1	2	1																		1		
	Heteronotia binoei	Bynoe's Gecko									2	2																				1	
Pygopodidae	*Delma australis*	Marble-faced Delma																						1									
	Delma nasuta	Sharp-snouted Delma		1					1																								
	Lialis burtonis	Burton's Legless Lizard					1																										
	Pygopus nigriceps	Western Hooded Scaly-foot					1	1																									
Scincidae	*Cryptoblepharus buchananii*	Buchanan's Snake-eyed Skink						1	3		4	1										1		1									
	Ctenotus atlas	Southern Mallee Ctenotus	3	4					1		4							7															
	Ctenotus brooksi	Wedgsnout Ctenotus		24															11														
	Ctenotus calurus	Blue-tailed Finesnout Ctenotus											1																				
	Ctenotus greeri	Spotted-necked Ctenotus											12																				
	Ctenotus helenae	Clay-soil Ctenotus											1																				
	Ctenotus leonhardii	Leonhardi's Ctenotus			5	9																	1				1	8	2	1			
	Ctenotus pantherinus	Leopard Ctenotus											4																				
	Ctenotus quattuordecimlineatus	Fourteen-lined Ctenotus											11																				
	Ctenotus schomburgkii	Barred Wedgesnout Ctenotus	9	4	1			3	5				11					1			1						1	1					
	Ctenotus uber	Spotted Ctenotus						1			6	1								2													
	Cyclodomorphus branchialis	Common Slender Bluetongue					1		2																								
	Egernia depressa	Southern Pygmy Spiny-tailed Skink						2	1		10																				3		
	Egernia formosa	Goldfields Crevice Skink									5																						
	Eremiascincus richardsonii	Broad-banded Sand-swimmer																						1									
	Lerista desertorum	Central Desert Robust Slider											6																				
	Lerista lineopunctulata	Dotted-line Robust Slider																	2				4										
	Lerista macropisthopus	Unpatterned Robust Slider							1																								
	Liopholis inornata	Desert Skink	1	3			1	1			1	1						1	1	2				1									
	Menetia greyii	Common Dwarf Skink	2	1	1			1	2		1										1						1			3		
	Morethia butleri	Woodland Morethia Skink								2	2	2																					
	Tiliqua occipitalis	Western Blue-tongued Lizard	1				1														4												
	Tiliqua rugosa	Bobtail																			3			1									
Typhlopidae	*Anilios hamatus*	Pale-headed Blind Snake																		1													

		Surveys	A															B									C						
Family	Species	Common name	Site 13	Site 3	Site 9	Site 9a	Site 12	Site 21	Site 22	Site 14	Site 15	Site 21a	Site 19	Freshwater	Goongarri	Salt Lake	Site 12a	Site 3	Site 5	Site 7	Site 4	Site 1	Site 6	Site 8	Opportunisti	Site 2	Site 1	Site 2	Site 3	Site 4	Site 5	Site 6	Site 9
Varanidae	*Varanus caudolineatus*	Stripe-tailed Monitor			1																			1			3	2					
	Varanus gouldii	Gould's Goanna			1	1		2				2						1		2													
	Varanus panoptes	Yellow-spotted Monitor																									1		2	1	2		
	Varanus tristis	Black-headed Monitor										3																					
Birds																																	
Casuariidae	*Dromaius novaehollandiae*	Emu	8	2	1				3		4	1	2	1	1	1									1								
Anatidae	*Cygnus atratus*	Black Swan																							1								
	Tadorna tadornoides	Australian Shelduck												1											1								
	Chenonetta jubata	Australian Wood Duck												1											1								
	Anas superciliosa	Pacific Black Duck												1											1								
	Anas gracilis	Grey Teal												1											1								
	Aythya australis	Hardhead																							1								
Columbidae	*Phaps chalcoptera*	Common Bronzewing							2			1		1	1	1	1								1								
	Ocyphaps lophotes	Crested Pigeon		2	6					1				1	1	1									1								
	Geopelia cuneata	Diamond Dove			1																												
Cuculidae	*Chrysococcyx basalis*	Horsfield's Bronze-Cuckoo	6		1				2		3	2	3		1	1									1		1	2	2	1			
	Chrysococcyx osculans	Black-eared Cuckoo	3	4					6		2		1		1												1				1		
Aegothelidae	*Aegotheles cristatus*	Australian Owlet-nightjar							3	3					1										1				1				
Podargidae	*Podargus strigoides*	Tawny Frogmouth							1						1										1								
Caprimulgidae	*Eurostopodus argus*	Spotted Nightjar														1																	
Rallidae	*Tribonyx ventralis*	Black-tailed Nativehen												1																			
Recurvirostridae	*Himantopus leucocephalus*	Pied Stilt																							1								
	Cladorhynchus leucocephalus	Banded Stilt														1									1								
	Recurvirostra novaehollandiae	Red-necked Avocet												1											1								
Charadriidae	*Charadrius ruficapillus*	Red-capped Plover												1																			
	Erythrogonys cinctus	Red-kneed Dotterel																							1								
	Elseyornis melanops	Black-fronted Dotterel												1																			
Scolopacidae	*Tringa nebularia*	Common Greenshank																							1								
Turnicidae	*Turnix velox*	Little Buttonquail	13	3											1																		
Laridae	*Chroicocephalus novaehollandiae*	Silver Gull																							1								
Ardeidae	*Ardea pacifica*	White-necked Heron												1											1								
	Egretta novaehollandiae	White-faced Heron												1	1										1								
Threskiornithidae	*Platalea flavipes*	Yellow-billed Spoonbill																							1								

		Surveys	A														B								C						
Family	Species	Common name	Site 13	Site 3	Site 9	Site 9a	Site 12	Site 21	Site 22	Site 14	Site 15	Site 21a	Site 19	Freshwater	Goongarri	Salt Lake	Site 12a	Site 3	Site 5	Site 7	Site 4	Site 1	Site 6	Site 8	Opportunisti	Site 2	Site 1	Site 2	Site 3	Site 4	Site 5	Site 6	Site 9
Ardeidae	*Ardea alba*	Great Egret																							1								
Accipitridae	*Elanus axillaris*	Black-shouldered Kite																							1								
	Lophoictinia isura	Square-tailed Kite																							1								
	Hieraaetus morphnoides	Little Eagle		1					2				3		1										1								
	Aquila audax	Wedge-tailed Eagle								6					1										1								
	Circus assimilis	Spotted Harrier						1							1																		
	Accipiter fasciatus	Brown Goshawk									1		3		1	1									1								
	Accipiter cirrocephalus	Collared Sparrowhawk													1	1									1								
Cuculidae	*Heteroscenes pallidus*	Pallid Cuckoo						4		2			1		1													1	2	2	1		
Strigidae	*Ninox boobook*	Southern Boobook													1																		
Alcedinidae	*Todiramphus pyrrhopygius*	Red-backed Kingfisher												1	1										1								
Meropidae	*Merops ornatus*	Rainbow Bee-eater	3	1					5				3		1										1								
Falconidae	*Falco cenchroides*	Nankeen Kestrel											3		1										1								
	Falco longipennis	Australian Hobby							1						1										1								
	Falco berigora	Brown Falcon		2					2		2		5		1										1								
	Falco peregrinus	Peregrine Falcon																							1								
Timaliidae	*Zosterops lateralis*	Silvereye																							1								
Cacatuidae	*Eolophus roseicapilla*	Galah							4	44	5	62	5	1	1	1									1			2			2		
	Nymphicus hollandicus	Cockatiel							11			4	3	1	1	1											13	3		21	3		
Psittacidae	*Neopsephotus bourkii*	Bourke's Parrot												1	1	1														5			
	Neophema splendida	Scarlet-chested Parrot									2																						
	Barnardius zonarius	Australian Ringneck			10			3		25	8		16	1	1										1		8	5	8	5	5		
	Psephotus varius	Mulga Parrot	4	4	3			2			4		2		1										1								
	Melopsittacus undulatus	Budgerigar	1	6				38	27	11	1		29	1	1	1											10		20	15			
Ptilonorhynchidae	*Chlamydera guttata*	Western Bowerbird																										1					
Climacteridae	*Climacteris affinis*	White-browed Treecreeper						1				1			1																		
Maluridae	*Malurus pulcherrimus*	Blue-breasted Fairywren	15	9																					1								
	Malurus splendens	Splendid Fairywren	24								34				1										1		15	10	20	14	21		
	Malurus leucopterus	White-winged Fairywren			17									1	1	1									1								
Meliphagidae	*Certhionyx variegatus*	Pied Honeyeater	2							2	3				1	1																	
	Purnella albifrons	White-fronted Honeyeater	69	125	16			7	144	3	12	6	4		1	1	4								1								
	Manorina flavigula	Yellow-throated Miner			109			3	74	10			13		1										1				1	7			
	Acanthagenys rufogularis	Spiny-cheeked Honeyeater	18	23	7			6	52	11	30	4	8	1	1	1									1		1	1	5	5	6		

		Surveys	A														B								C						
Family	Species	Common name	Site 13	Site 3	Site 9	Site 9a	Site 12	Site 21	Site 22	Site 14	Site 15	Site 21a	Site 19	Freshwater	Goongarri	Salt Lake	Site 12a	Site 3	Site 5	Site 7	Site 4	Site 1	Site 6	Site 8	Opportunisti	Site 2	Site 1	Site 2	Site 3	Site 4	Site 5	Site 6	Site 9
	Anthochaera carunculata	Red Wattlebird			1				5				2												1				2	5			
	Gavicalis virescens	Singing Honeyeater	2		4				1	11	2		2	1	1	1									1		1	1	1	2	2		
	Ptilotula ornata	Yellow-plumed Honeyeater							230						1										1								
	Ptilotula plumula	Grey-fronted Honeyeater							12	56			3			1																	
	Conopophila whitei	Grey Honeyeater	2		1							17			1	1																	
	Epthianura tricolor	Crimson Chat								154																		2					
	Epthianura albifrons	White-fronted Chat												1	1										1								
	Sugomel nigrum	Black Honeyeater	7	4							3																						
	Lichmera indistincta	Brown Honeyeater													1										1								
	Nesoptilotis leucotis	White-eared Honeyeater	4																						1								
	Melithreptus brevirostris	Brown-headed Honeyeater							6						1										1								
Pardalotidae	*Pardalotus striatus*	Striated Pardalote		1					2				2		1										1								
Acanthizidae	*Pyrrholaemus brunneus*	Redthroat	16	8				2			4	1			1										1			1			2		
	Calamanthus campestris	Rufous Fieldwren																													1		
	Acanthiza iredalei	Slender-billed Thornbill													1																		
	Acanthiza apicalis	Inland Thornbill	32	38				1	15		18	2	3		1		2								1		19	10	18	11	16		
	Acanthiza chrysorrhoa	Yellow-rumped Thornbill	2		4				1		48		4												1			2					
	Acanthiza uropygialis	Chestnut-rumped Thornbill	23	3	27				46		86	10	88		1	1	2								1								
	Acanthiza robustirostris	Slaty-backed Thornbill											3														5	5	14	8	12		
	Smicrornis brevirostris	Weebill	50	36				2	269			2	98		1										1		2		10	5			
	Aphelocephala leucopsis	Southern Whiteface									153	12	5		1										1								
Pomatostomidae	*Pomatostomus superciliosus*	White-browed Babbler	1								4	3			1										1			3					
Cinclosomatidae	*Cinclosoma castanotum*	Chestnut Quail-thrush							3		1																						
Campephagidae	*Coracina maxima*	Ground Cuckooshrike							6						1																		
	Coracina novaehollandiae	Black-faced Cuckooshrike		11	3				12	4	15		9		1										1				2				
	Lalage tricolor	White-winged Triller	2		2				14		3	6			1	1																	
Neosittidae	*Daphoenositta chrysoptera*	Varied Sittella	2										6		1																		
Oreoicidae	*Oreoica gutturalis*	Crested Bellbird	11	6	2				15	14	18	2	15		1		1								1		6	8	6	5	5		
Pachycephalidae	*Colluricincla harmonica*	Grey Shrikethrush	6	16					17		5	1	5		1										1		2	2	2	1	3		
	Pachycephala rufiventris	Rufous Whistler		2					32		13	1	8		1	1									1		2		1				
Artamidae	*Artamus personatus*	Masked Woodswallow	1	1					18	2			2		1	1																	
	Artamus cinereus	Black-faced Woodswallow								55		1			1	1									1								
	Cracticus torquatus	Grey Butcherbird	2	2	1				8	2			8		1	1									1								

		Surveys	A														B								C						
Family	Species	Common name	Site 13	Site 3	Site 9	Site 9a	Site 12	Site 21	Site 22	Site 14	Site 15	Site 21a	Site 19	Freshwater	Goongarri	Salt Lake	Site 12a	Site 3	Site 5	Site 7	Site 4	Site 1	Site 6	Site 8	Opportunisti	Site 2	Site 1	Site 2	Site 3	Site 4	Site 5	Site 6	Site 9
	Cracticus nigrogularis	Pied Butcherbird	3	2	14				5	6	1	2	4		1										1			1	1	2	1		
	Gymnorhina tibicen	Australian Magpie			5				2																1								
	Strepera versicolor	Grey Currawong			4				1		1	1	2		1										1		3	1	5	1	4		
Rhipiduridae	*Rhipidura leucophrys*	Willie Wagtail			1				5					1	1	1									1								
	Rhipidura albiscapa	Grey Fantail							13						1										1		1						
Monarchidae	*Grallina cyanoleuca*	Magpie-lark												1											1								
Corvidae	*Corvus orru*	Torresian Crow							2																1		3	2	4				
	Corvus bennetti	Little Crow			149				7	29	10		24	1	1										1		1		1	1			
Petroicidae	*Microeca fascinans*	Jacky Winter							28				22		1	1									1								
	Petroica goodenovii	Red-capped Robin	8		4				20	1	106	4	29		1	1									1			4	4	5	3		
	Melanodryas cucullata	Hooded Robin		2					32	2	13	1			1	1																	
Locustellidae	*Cincloramphus cruralis*	Brown Songlark								3					1																		
	Cincloramphus mathewsi	Rufous Songlark										2			1										1								
Hirundinidae	*Hirundo neoxena*	Welcome Swallow	2	1										1	1	1									1								
	Petrochelidon ariel	Fairy Martin		5											1										1								
	Petrochelidon nigricans	Tree Martin		7										1											1								
	Cheramoeca leucosterna	White-backed Swallow												1	1										1								
Dicaeidae	*Dicaeum hirundinaceum*	Mistletoebird	3	1	4			1	5						1										1								
Estrildidae	*Taeniopygia guttata*	Zebra Finch (Australian)		4					2	12	2		5	1	1										1								
Motacillidae	*Anthus novaeseelandiae*	Australasian Pipit			2				4					1	1	1									1								
Mammals																																	
Tachyglossidae	*Tachyglossus aculeatus*	Short-beaked Echidna									1								1	1						1							
Bovidae	*Capra hircus*	Goat								1			1																				
	Ovis aries	Sheep			1	1		1					1																				
Camelidae	*Camelus dromedarius*	Dromedary							1																								
Canidae	*Canis lupus*	Dingo	1						1																								
	Vulpes vulpes	Red Fox	1	1							1	1	1																				
Felidae	*Felis catus*	Cat		1																													
Molossidae	*Austronomus australis*	White-striped Freetail Bat							1																		1	1	1	1	1		
Vespertilionidae	*Chalinolobus gouldii*	Gould's Wattled Bat																									1	1	1	1	1		
	Scotorepens balstoni	Inland Broad-nosed Bat																									1	1	1	1			
	Vespadelus finlaysoni	Finlayson's Cave Bat																									1	1	1	1	1		
	Vespadelus regulus	Southern Forest Bat																															

		Surveys	A															B									C						
Family	Species	Common name	Site 13	Site 3	Site 9	Site 9a	Site 12	Site 21	Site 22	Site 14	Site 15	Site 21a	Site 19	Freshwater	Goongarri	Salt Lake	Site 12a	Site 3	Site 5	Site 7	Site 4	Site 1	Site 6	Site 8	Opportunisti	Site 2	Site 1	Site 2	Site 3	Site 4	Site 5	Site 6	Site 9
Dasyuridae	*Ningaui ridei*	Wongai Ningaui	1	3									5					2															
	Pseudantechinus woolleyae	Woolley's False Antechinus																															1
	Sminthopsis crassicaudata	Fat-tailed Dunnart		1		1																	1	1									
	Sminthopsis dolichura	Little Long-tailed Dunnart	3					1	1				1						2		2	2		2			1	2	3	4	3		
	Sminthopsis longicaudata	Long-tailed Dunnart																											2				
Burramyidae	*Cercartetus concinnus*	Southwestern Pygmy Possum																				1		1									
Macropodidae	*Osphranter robustus*	Euro						1					1																				
	Osphranter rufus	Red Kangaroo								1																							
Leporidae	*Oryctolagus cuniculus*	Rabbit		1																													
Muridae	*Mus musculus*	House Mouse	4	2									3													4	4	2	2	23	10		1
	Notomys alexis	Spinifex Hopping Mouse	2	9				2	1		1																5						
	Notomys mitchellii	Mitchell's Hopping Mouse		3				1																									
	Pseudomys bolami	Bolam's Mouse										3						1	3														
	Pseudomys hermannsburgensis	Sandy Inland Mouse	2	1									7					1									3		1	2	1		

A Dell, J and How, R.A. (1988) Vertebrate fauna in The biological survey of the eastern goldfields of Western Australia Part 5: Edjudina - Menzies Study Area, *Records of the Western Australian Museum*, Supplement No. 31, 38-69.

B Hart Simpson and Associates (2000) *Anaconda Nickel Ltd, Cawse Expansion Project, Fauna Survey*, Unpublished report for Anaconda Nickel Ltd, Perth

C Keith Lindbeck and Associates (2012) *Central Yilgarn Iron Project (CYIP) Fauna Assessment*, Unpublished report for Jupiter Mines Ltd, Perth.

Appendix C. Definitions of significant fauna under the WA *Biodiversity Conservation Act 2016* and Priority Species

Basic Vertebrate Fauna Survey and Risk Assessment
Menzies Mining Project



ATTACHMENT C
DEFINITIONS OF SIGNIFICANT FAUNA UNDER THE WA BIODIVERSITY CONSERVATION ACT 2016

Threatened, Extinct and Specially Protected fauna or flora[1] are species[2] which have been adequately searched for and are deemed to be, in the wild, threatened, extinct or in need of special protection, and have been gazetted as such. The *Wildlife Conservation (Specially Protected Fauna) Notice 2018* and the *Wildlife Conservation (Rare Flora) Notice 2018* have been transitioned under regulations 170, 171 and 172 of the *Biodiversity Conservation Regulations 2018* to be the lists of Threatened, Extinct and Specially Protected species under Part 2 of the *Biodiversity Conservation Act 2016*. Categories of Threatened, Extinct and Specially Protected fauna and flora are:

T Threatened Species

Listed by order of the Minister as Threatened in the category of critically endangered, endangered or vulnerable under section 19(1), or is a rediscovered species to be regarded as threatened species under section 26(2) of the *Biodiversity Conservation Act 2016* (BC Act).

Threatened fauna is that subset of 'Specially Protected Fauna' listed under schedules 1 to 3 of the *Wildlife Conservation (Specially Protected Fauna) Notice 2018* for Threatened Fauna.

Threatened flora is that subset of 'Rare Flora' listed under schedules 1 to 3 of the *Wildlife Conservation (Rare Flora) Notice 2018* for Threatened Flora.

The assessment of the conservation status of these species is based on their national extent and ranked according to their level of threat using IUCN Red List categories and criteria as detailed below.

CR Critically endangered species

Threatened species considered to be "*facing an extremely high risk of extinction in the wild in the immediate future, as determined in accordance with criteria set out in the ministerial guidelines*".

Listed as critically endangered under section 19(1)(a) of the BC Act in accordance with the criteria set out in section 20 and the ministerial guidelines. Published under schedule 1 of the *Wildlife Conservation (Specially Protected Fauna) Notice 2018* for critically endangered fauna or the *Wildlife Conservation (Rare Flora) Notice 2018* for critically endangered flora.

[1] The definition of flora includes algae, fungi and lichens

[2] Species includes all taxa (plural of taxon - a classificatory group of any taxonomic rank, e.g. a family, genus, species or any infraspecific category i.e. subspecies or variety, or a distinct population).

EN Endangered species

Threatened species considered to be "*facing a very high risk of extinction in the wild in the near future, as determined in accordance with criteria set out in the ministerial guidelines*".

Listed as endangered under section 19(1)(b) of the BC Act in accordance with the criteria set out in section 21 and the ministerial guidelines. Published under schedule 2 of the *Wildlife Conservation (Specially Protected Fauna) Notice 2018* for endangered fauna or the *Wildlife Conservation (Rare Flora) Notice 2018* for endangered flora.

VU Vulnerable species

Threatened species considered to be "*facing a high risk of extinction in the wild in the medium-term future, as determined in accordance with criteria set out in the ministerial guidelines*".

Listed as vulnerable under section 19(1)(c) of the BC Act in accordance with the criteria set out in section 22 and the ministerial guidelines. Published under schedule 3 of the *Wildlife Conservation (Specially Protected Fauna) Notice 2018* for vulnerable fauna or the *Wildlife Conservation (Rare Flora) Notice 2018* for vulnerable flora.

Extinct Species

Listed by order of the Minister as extinct under section 23(1) of the BC Act as extinct or extinct in the wild.

EX Extinct species

Species where "*there is no reasonable doubt that the last member of the species has died*", and listing is otherwise in accordance with the ministerial guidelines (section 24 of the BC Act).

Published as presumed extinct under schedule 4 of the *Wildlife Conservation (Specially Protected Fauna) Notice 2018* for extinct fauna or the *Wildlife Conservation (Rare Flora) Notice 2018* for extinct flora.

EW Extinct in the wild species

Species that "*is known only to survive in cultivation, in captivity or as a naturalised population well outside its past range; and it has not been recorded in its known habitat or expected habitat, at appropriate seasons, anywhere in its past range, despite surveys over a time frame appropriate to its life cycle and form*", and listing is otherwise in accordance with the ministerial guidelines (section 25 of the BC Act).

Currently there are no threatened fauna or threatened flora species listed as extinct in the pwild. If listing of a species as extinct in the wild occurs, then a schedule will be added to the applicable notice.

Specially Protected Species

Listed by order of the Minister as specially protected under section 13(1) of the BC Act. Meeting one or more of the following categories: species of special conservation interest; migratory species; cetaceans; species subject to international agreement; or species otherwise in need of special protection.

Species that are listed as threatened species (critically endangered, endangered or vulnerable) or extinct species under the BC Act cannot also be listed as Specially Protected species.

MI Migratory birds protected under an international agreement

Fauna that periodically or occasionally visit Australia or an external Territory or the exclusive economic zone; or the species is subject of an international agreement that relates to the protection of migratory species and that binds the Commonwealth; and listing is otherwise in accordance with the ministerial guidelines (section 15 of the BC Act).

Includes birds that are subject to an agreement between the government of Australia and the governments of Japan (JAMBA), China (CAMBA) and The Republic of Korea (ROKAMBA), and fauna subject to the *Convention on the Conservation of Migratory Species of Wild Animals* (Bonn Convention), an environmental treaty under the United Nations Environment Program. Migratory species listed under the BC Act are a subset of the migratory animals, that are known to visit Western Australia, protected under the international agreements or treaties, excluding species that are listed as Threatened species.

Published as migratory birds protected under an international agreement under schedule 5 of the *Wildlife Conservation (Specially Protected Fauna) Notice 2018*.

CD Species of special conservation interest (conservation dependant fauna)

Fauna of special conservation need being species dependent on ongoing conservation intervention to prevent it becoming eligible for listing as threatened, and listing is otherwise in accordance with the ministerial guidelines (section 14 of the BC Act).

Published as conservation dependent fauna under schedule 6 of the *Wildlife Conservation (Specially Protected Fauna) Notice 2018*.

OS Other specially protected species

Fauna otherwise in need of special protection to ensure their conservation, and listing is otherwise in accordance with the ministerial guidelines (section 18 of the BC Act).

Published as other specially protected fauna under schedule 7 of the *Wildlife Conservation (Specially Protected Fauna) Notice 2018*.

P Priority species

Possibly threatened species that do not meet survey criteria, or are otherwise data deficient, are added to the Priority Fauna or Priority Flora Lists under Priorities 1, 2 or 3. These three categories are ranked in order of priority for survey and evaluation of conservation status so that consideration can be given to their declaration as threatened fauna or flora.

Species that are adequately known, are rare but not threatened, or meet criteria for near threatened, or that have been recently removed from the threatened species or other specially protected fauna lists for other than taxonomic reasons, are placed in Priority 4. These species require regular monitoring.

Assessment of Priority codes is based on the Western Australian distribution of the species, unless the distribution in WA is part of a contiguous population extending into adjacent States, as defined by the known spread of locations

P1 Priority 1: Poorly-known species

Species that are known from one or a few locations (generally five or less) which are potentially at risk. All occurrences are either: very small; or on lands not managed for conservation, e.g. agricultural or pastoral lands, urban areas, road and rail reserves, gravel reserves and active mineral leases; or otherwise under threat of habitat destruction or degradation. Species may be included if they are comparatively well known from one or more locations but do not meet adequacy of survey requirements and appear to be under immediate threat from known threatening processes. Such species are in urgent need of further survey.

P2 Priority 2: Poorly-known species

Species that are known from one or a few locations (generally five or less), some of which are on lands managed primarily for nature conservation, e.g. national parks, conservation parks, nature reserves and other lands with secure tenure being managed for conservation. Species may be included if they are comparatively well known from one or more locations but do not meet adequacy of survey requirements and appear to be under threat from known threatening processes. Such species are in urgent need of further survey.

P3 Priority 3: Poorly-known species

Species that are known from several locations, and the species does not appear to be under imminent threat, or from few but widespread locations with either large population size or significant remaining areas of apparently suitable habitat, much of it not under imminent threat. Species may be included if they are comparatively well known from several locations but do not meet adequacy of survey requirements and known threatening processes exist that could affect them. Such species are in need of further survey.

P4 Priority 4: Rare, Near Threatened and other species in need of monitoring

(a) Rare. Species that are considered to have been adequately surveyed, or for which sufficient knowledge is available, and that are considered not currently threatened or in need of special protection but could be if present circumstances change. These species are usually represented on conservation lands.

(b) Near Threatened. Species that are considered to have been adequately surveyed and that are close to qualifying for vulnerable but are not listed as Conservation Dependent.

(c) Species that have been removed from the list of threatened species during the past five years for reasons other than taxonomy.

Appendix D.
Rapid habitat assessment

Basic Vertebrate Fauna Survey and Risk Assessment
Menzies Mining Project



Date: 15/11/2021

Habitat Assessment #: 1

Observer: ST

Zone: 51

Easting: 307844 mE

Northing: 6713678 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021

Habitat Assessment #: 2

Observer: ST

Zone: 51

Easting: 307959 mE

Northing: 6713540 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021

Habitat Assessment #: 3

Observer: ST

Zone: 51

Easting: 307954 mE

Northing: 6714022 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 4 | Observer: ST

Zone: 51 | Easting: 307747 mE | Northing: 6714103 mN

Fire History: >5 years | Landform: Waste dump | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 5 | Observer: ST

Zone: 51 | Easting: 307737 mE | Northing: 6714003 mN

Fire History: >5 years | Landform: Waste dump | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



Date: 15/11/2021

Habitat Assessment #: 6

Observer: ST

Zone: 51

Easting: 307774 mE

Northing: 6713774 mN

Fire History: >5 years


Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Disturbed



Date: 15/11/2021 | Habitat Assessment #: 7 | Observer: ST

Zone: 51 | Easting: 307770 mE | Northing: 6713504 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 8 | Observer: ST

Zone: 51 | Easting: 307948 mE | Northing: 6713800 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 9 | Observer: ST

Zone: 51 | Easting: 307560 mE | Northing: 6713525 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 10 | Observer: ST

Zone: 51 | Easting: 307549 mE | Northing: 6713785 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 11 | Observer: ST

Zone: 51 | Easting: 307540 mE | Northing: 6713971 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 12 | Observer: ST

Zone: 51 | Easting: 307537 mE | Northing: 6714122 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 13 | Observer: ST

Zone: 51 | Easting: 307321 mE | Northing: 6714057 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 14 | Observer: ST

Zone: 51 | Easting: 307356 mE | Northing: 6713807 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 15 | Observer: ST

Zone: 51 | Easting: 307154 mE | Northing: 6714096 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 16 | Observer: ST

Zone: 51 | Easting: 307356 mE | Northing: 6714198 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 17 | Observer: ST

Zone: 51 | Easting: 307518 mE | Northing: 6714377 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS


Date: 15/11/2021 | Habitat Assessment #: 18 | Observer: ST

Zone: 51 | Easting: 307528 mE | Northing: 6714568 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 19 | Observer: ST

Zone: 51 | Easting: 307350 mE | Northing: 6714614 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 20 | Observer: ST

Zone: 51 | Easting: 307336 mE | Northing: 6714949 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 21 | Observer: ST

Zone: 51 | Easting: 307462 mE | Northing: 6715050 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 22 | Observer: ST

Zone: 51 | Easting: 307520 mE | Northing: 6714802 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 23 | Observer: ST

Zone: 51 | Easting: 307708 mE | Northing: 6714350 mN

Fire History: >5 years | Landform: Waste dump | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 24 | Observer: ST

Zone: 51 | Easting: 307709 mE | Northing: 6714466 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS


Date: 15/11/2021 | Habitat Assessment #: 25 | Observer: ST

Zone: 51 | Easting: 307709 mE | Northing: 6714819 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 26 | Observer: ST

Zone: 51 | Easting: 307680 mE | Northing: 6715024 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 27 | Observer: ST

Zone: 51 | Easting: 308126 mE | Northing: 6714930 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 28 | Observer: ST

Zone: 51 | Easting: 307873 mE | Northing: 6714818 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 29 | Observer: ST

Zone: 51 | Easting: 308090 mE | Northing: 6714619 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021

Habitat Assessment #: 30

Observer: ST

Zone: 51

Easting: 307944 mE

Northing: 6714266 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Clay

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 31 | Observer: ST

Zone: 51 | Easting: 308141 mE | Northing: 6714197 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS


Date: 15/11/2021 | Habitat Assessment #: 32 | Observer: ST

Zone: 51 | Easting: 308346 mE | Northing: 6714275 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 33 | Observer: ST

Zone: 51 | Easting: 308300 mE | Northing: 6714648 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 34 | Observer: ST


Zone: 51 | Easting: 308307 mE | Northing: 6714933 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 35 | Observer: ST

Zone: 51 | Easting: 308485 mE | Northing: 6714990 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 36 | Observer: ST

Zone: 51 | Easting: 308485 mE | Northing: 6714653 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS


Date: 15/11/2021 | Habitat Assessment #: 37 | Observer: ST

Zone: 51 | Easting: 308513 mE | Northing: 6714432 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 38 | Observer: ST

Zone: 51 | Easting: 308528 mE | Northing: 6714039 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded





TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 39 | Observer: ST

Zone: 51 | Easting: 308714 mE | Northing: 6714093 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 40 | Observer: ST

Zone: 51 | Easting: 308699 mE | Northing: 6714464 mN

Fire History: >5 years | Landform: Creekline | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 41 | Observer: ST

Zone: 51 | Easting: 308694 mE | Northing: 6714655 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Rock

Habitat Structure: Rocky ridge with shrubs | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 42 | Observer: ST

Zone: 51 | Easting: 308676 mE | Northing: 6714949 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021 | Habitat Assessment #: 43 | Observer: ST

Zone: 51 | Easting: 308734 mE | Northing: 6713822 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 15/11/2021

Habitat Assessment #: 44

Observer: ST

Zone: 51

Easting: 308598 mE

Northing: 6713651 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Clay

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Disturbed



Date: 16/11/2021 | Habitat Assessment #: 45 | Observer: ST

Zone: 51 | Easting: 308195 mE | Northing: 6713825 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 46 | Observer: ST

Zone: 51 | Easting: 308599 mE | Northing: 6712874 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 47 | Observer: ST

Zone: 51 | Easting: 308398 mE | Northing: 6712719 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 48 | Observer: ST

Zone: 51 | Easting: 308199 mE | Northing: 6712585 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 49 | Observer: ST

Zone: 51 | Easting: 308004 mE | Northing: 6712434 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 50 | Observer: ST

Zone: 51 | Easting: 307833 mE | Northing: 6712292 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 51 | Observer: ST

Zone: 51 | Easting: 307937 mE | Northing: 6712045 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 52 | Observer: ST

Zone: 51 | Easting: 308222 mE | Northing: 6712177 mN

Fire History: >5 years | Landform: Waste dump | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 53 | Observer: ST

Zone: 51 | Easting: 308418 mE | Northing: 6712321 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 54 | Observer: ST

Zone: 51 | Easting: 308424 mE | Northing: 6712115 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 55 | Observer: ST

Zone: 51 | Easting: 308237 mE | Northing: 6711982 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 56 | Observer: ST

Zone: 51 | Easting: 308052 mE | Northing: 6711830 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 57 | Observer: ST

Zone: 51 | Easting: 308247 mE | Northing: 6711746 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 58 | Observer: ST

Zone: 51 | Easting: 308449 mE | Northing: 6711893 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 59 | Observer: ST

Zone: 51 | Easting: 308633 mE | Northing: 6712002 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 60 | Observer: ST

Zone: 51 | Easting: 308837 mE | Northing: 6711733 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 61 | Observer: ST

Zone: 51 | Easting: 308664 mE | Northing: 6711519 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 62 | Observer: ST

Zone: 51 | Easting: 308460 mE | Northing: 6711398 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 63 | Observer: ST

Zone: 51 | Easting: 308483 mE | Northing: 6711242 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 64 | Observer: ST

Zone: 51 | Easting: 308499 mE | Northing: 6711127 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 65 | Observer: ST

Zone: 51 | Easting: 308673 mE | Northing: 6711180 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 66 | Observer: ST

Zone: 51 | Easting: 308796 mE | Northing: 6711274 mN

Fire History: >5 years | Landform: Gentle slope | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 67 | Observer: ST

Zone: 51 | Easting: 309069 mE | Northing: 6711485 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 68 | Observer: ST

Zone: 51 | Easting: 309220 mE | Northing: 6711223 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 69 | Observer: ST

Zone: 51 | Easting: 309053 mE | Northing: 6711091 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 70 | Observer: ST

Zone: 51 | Easting: 308867 mE | Northing: 6710952 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 71 | Observer: ST

Zone: 51 | Easting: 308690 mE | Northing: 6710817 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 Habitat Assessment #: 72 Observer: ST

Zone: 51 Easting: 308896 mE Northing: 6710438 mN

Fire History: >5 years Landform: Flat plain Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 73 | Observer: ST

Zone: 51 | Easting: 309119 mE | Northing: 6710496 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 74 | Observer: ST

Zone: 51 | Easting: 309307 mE | Northing: 6710595 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 75 | Observer: ST

Zone: 51 | Easting: 309516 mE | Northing: 6710692 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 76 | Observer: ST

Zone: 51 | Easting: 309492 mE | Northing: 6710353 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 77 | Observer: ST

Zone: 51 | Easting: 309325 mE | Northing: 6710263 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 78 | Observer: ST

Zone: 51 | Easting: 309088 mE | Northing: 6710222 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 79 | Observer: ST

Zone: 51 | Easting: 309170 mE | Northing: 6710019 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 80 | Observer: ST

Zone: 51 | Easting: 309340 mE | Northing: 6710046 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 81 | Observer: ST

Zone: 51 | Easting: 309554 mE | Northing: 6710001 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 82 | Observer: ST

Zone: 51 | Easting: 309344 mE | Northing: 6709803 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 83 | Observer: ST

Zone: 51 | Easting: 309574 mE | Northing: 6709761 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 84 | Observer: ST

Zone: 51 | Easting: 309526 mE | Northing: 6709470 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 85 | Observer: ST

Zone: 51 | Easting: 309762 mE | Northing: 6709567 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 86 | Observer: ST

Zone: 51 | Easting: 309778 mE | Northing: 6709303 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 87 | Observer: ST

Zone: 51 | Easting: 309784 mE | Northing: 6709026 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 88 | Observer: ST

Zone: 51 | Easting: 310001 mE | Northing: 6708776 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 89 | Observer: ST

Zone: 51 | Easting: 310021 mE | Northing: 6709106 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 90 | Observer: ST

Zone: 51 | Easting: 309972 mE | Northing: 6709375 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 91 | Observer: ST

Zone: 51 | Easting: 309906 mE | Northing: 6709632 mN

Fire History: >5 years | Landform: Waste dump | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021

Habitat Assessment #: 92

Observer: ST

Zone: 51

Easting: 309875 mE

Northing: 6709718 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 93 | Observer: ST

Zone: 51 | Easting: 310148 mE | Northing: 6709974 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 94 | Observer: ST

Zone: 51 | Easting: 310185 mE | Northing: 6709586 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 95 | Observer: ST

Zone: 51 | Easting: 310195 mE | Northing: 6709293 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 96 | Observer: ST

Zone: 51 | Easting: 310192 mE | Northing: 6708990 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 97 | Observer: ST

Zone: 51 | Easting: 310191 mE | Northing: 6708741 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 98 | Observer: ST

Zone: 51 | Easting: 310252 mE | Northing: 6708392 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 99 | Observer: ST

Zone: 51 | Easting: 310254 mE | Northing: 6708126 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Low grasses | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 100 | Observer: ST

Zone: 51 | Easting: 310263 mE | Northing: 6707864 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 101 | Observer: ST

Zone: 51 | Easting: 310037 mE | Northing: 6708043 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 102 | Observer: ST

Zone: 51 | Easting: 310086 mE | Northing: 6707673 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 103 | Observer: ST

Zone: 51 | Easting: 309885 mE | Northing: 6707635 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 104 | Observer: ST

Zone: 51 | Easting: 310290 mE | Northing: 6707657 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 105 | Observer: ST

Zone: 51 | Easting: 310307 mE | Northing: 6707364 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 106 | Observer: ST

Zone: 51 | Easting: 310088 mE | Northing: 6707329 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: SST

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 107 | Observer: ST

Zone: 51 | Easting: 310114 mE | Northing: 6707068 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 108 | Observer: ST

Zone: 51 | Easting: 310298 mE | Northing: 6707070 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 109 | Observer: ST

Zone: 51 | Easting: 310320 mE | Northing: 6706805 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 110 | Observer: ST

Zone: 51 | Easting: 310347 mE | Northing: 6706541 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 111 | Observer: ST

Zone: 51 | Easting: 310563 mE | Northing: 6706512 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 112 | Observer: ST

Zone: 51 | Easting: 310475 mE | Northing: 6706839 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 113 | Observer: ST

Zone: 51 | Easting: 310480 mE | Northing: 6707109 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 114 | Observer: ST

Zone: 51 | Easting: 310474 mE | Northing: 6707377 mN

Fire History: >5 years | Landform: Creekline | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 115 | Observer: ST

Zone: 51 | Easting: 310435 mE | Northing: 6707460 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 116 | Observer: ST

Zone: 51 | Easting: 310437 mE | Northing: 6707677 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 117 | Observer: ST

Zone: 51 | Easting: 310425 mE | Northing: 6708034 mN

Fire History: >5 years | Landform: Creekline | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 118 | Observer: ST

Zone: 51 | Easting: 310414 mE | Northing: 6708290 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 119 | Observer: ST

Zone: 51 | Easting: 310413 mE | Northing: 6708637 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 120 | Observer: ST

Zone: 51 | Easting: 310374 mE | Northing: 6708990 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 121 | Observer: ST

Zone: 51 | Easting: 310386 mE | Northing: 6709330 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 122 | Observer: ST

Zone: 51 | Easting: 310341 mE | Northing: 6709616 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 123 | Observer: ST

Zone: 51 | Easting: 310372 mE | Northing: 6709953 mN

Fire History: >5 years | Landform: Creekline | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 124 | Observer: ST

Zone: 51 | Easting: 310381 mE | Northing: 6710058 mN

Fire History: >5 years | Landform: Creekline | Soil Type: Clay

Habitat Structure: Rocky ridge with shrubs | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 125 | Observer: ST

Zone: 51 | Easting: 310390 mE | Northing: 6710110 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Rocky ridge with shrubs | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 126 | Observer: ST

Zone: 51 | Easting: 310288 mE | Northing: 6710294 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 127 | Observer: ST

Zone: 51 | Easting: 310525 mE | Northing: 6710423 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 128 | Observer: ST

Zone: 51 | Easting: 310532 mE | Northing: 6710098 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 129 | Observer: ST

Zone: 51 | Easting: 310517 mE | Northing: 6709795 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 130 | Observer: ST

Zone: 51 | Easting: 310589 mE | Northing: 6709490 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 131 | Observer: ST

Zone: 51 | Easting: 310618 mE | Northing: 6709176 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021

Habitat Assessment #: 132

Observer: ST

Zone: 51

Easting: 310585 mE

Northing: 6708855 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: shrubland

Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 133 | Observer: ST

Zone: 51 | Easting: 310596 mE | Northing: 6708522 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 134 | Observer: ST

Zone: 51 | Easting: 310666 mE | Northing: 6708180 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 135 | Observer: ST

Zone: 51 | Easting: 310697 mE | Northing: 6707891 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 136 | Observer: ST

Zone: 51 | Easting: 310646 mE | Northing: 6707583 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 137 | Observer: ST

Zone: 51 | Easting: 310693 mE | Northing: 6707268 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 138 | Observer: ST

Zone: 51 | Easting: 310689 mE | Northing: 6706991 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 139 | Observer: ST

Zone: 51 | Easting: 310680 mE | Northing: 6706690 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 140 | Observer: ST

Zone: 51 | Easting: 310705 mE | Northing: 6706438 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 141 | Observer: ST

Zone: 51 | Easting: 310925 mE | Northing: 6706533 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 142 | Observer: ST

Zone: 51 | Easting: 310889 mE | Northing: 6706847 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 143 | Observer: ST

Zone: 51 | Easting: 310915 mE | Northing: 6707178 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 144 | Observer: ST

Zone: 51 | Easting: 310862 mE | Northing: 6707513 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 145 | Observer: ST

Zone: 51 | Easting: 310882 mE | Northing: 6707846 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 146 | Observer: ST

Zone: 51 | Easting: 310809 mE | Northing: 6708166 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 147 | Observer: ST

Zone: 51 | Easting: 310800 mE | Northing: 6708503 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 148 | Observer: ST

Zone: 51 | Easting: 310820 mE | Northing: 6708829 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 149 | Observer: ST

Zone: 51 | Easting: 310773 mE | Northing: 6709205 mN

Fire History: >5 years | Landform: Gentle slope | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 150 | Observer: ST

Zone: 51 | Easting: 310807 mE | Northing: 6709504 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 151 | Observer: ST

Zone: 51 | Easting: 310748 mE | Northing: 6709845 mN

Fire History: >5 years | Landform: Gentle slope | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 152 | Observer: ST

Zone: 51 | Easting: 310688 mE | Northing: 6710169 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 153 | Observer: ST

Zone: 51 | Easting: 310710 mE | Northing: 6710472 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 154 | Observer: ST

Zone: 51 | Easting: 310909 mE | Northing: 6709873 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 155 | Observer: ST

Zone: 51 | Easting: 310962 mE | Northing: 6709536 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 156 | Observer: ST

Zone: 51 | Easting: 310949 mE | Northing: 6709222 mN

Fire History: >5 years | Landform: Gentle slope | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 157 | Observer: ST

Zone: 51 | Easting: 310955 mE | Northing: 6708892 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 158 | Observer: ST

Zone: 51 | Easting: 311015 mE | Northing: 6708572 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 159 | Observer: ST

Zone: 51 | Easting: 311060 mE | Northing: 6708195 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 160 | Observer: ST

Zone: 51 | Easting: 311041 mE | Northing: 6707880 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 161 | Observer: ST

Zone: 51 | Easting: 311086 mE | Northing: 6707552 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 162 | Observer: ST

Zone: 51 | Easting: 311103 mE | Northing: 6707224 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 163 | Observer: ST

Zone: 51 | Easting: 311139 mE | Northing: 6706902 mN

Fire History: >5 years | Landform: Waste dump | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021

Habitat Assessment #: 164

Observer: ST

Zone: 51

Easting: 311172 mE

Northing: 6706810 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 165 | Observer: ST

Zone: 51 | Easting: 311124 mE | Northing: 6706614 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 166 | Observer: ST

Zone: 51 | Easting: 311142 mE | Northing: 6706362 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 167 | Observer: ST

Zone: 51 | Easting: 311316 mE | Northing: 6706345 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 168 | Observer: ST

Zone: 51 | Easting: 311288 mE | Northing: 6706528 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021

Habitat Assessment #: 169

Observer: ST

Zone: 51

Easting: 311560 mE

Northing: 6706302 mN

Fire History: >5 years

Landform: Waste dump

Soil Type: Clay

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021

Habitat Assessment #: 170

Observer: ST

Zone: 51

Easting: 311573 mE

Northing: 6706427 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 171 | Observer: ST

Zone: 51 | Easting: 311728 mE | Northing: 6706268 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 172 | Observer: ST

Zone: 51 | Easting: 310535 mE | Northing: 6706259 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 173 | Observer: ST

Zone: 51 | Easting: 310557 mE | Northing: 6706004 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 174 | Observer: ST

Zone: 51 | Easting: 310749 mE | Northing: 6706043 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 175 | Observer: ST

Zone: 51 | Easting: 310750 mE | Northing: 6705631 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 176 | Observer: ST

Zone: 51 | Easting: 310993 mE | Northing: 6705315 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 177 | Observer: ST

Zone: 51 | Easting: 310940 mE | Northing: 6705623 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 178 | Observer: ST

Zone: 51 | Easting: 310945 mE | Northing: 6705992 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 179 | Observer: ST

Zone: 51 | Easting: 310887 mE | Northing: 6706197 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 180 | Observer: ST

Zone: 51 | Easting: 311174 mE | Northing: 6706168 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 181 | Observer: ST

Zone: 51 | Easting: 311178 mE | Northing: 6705869 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 182 | Observer: ST

Zone: 51 | Easting: 311178 mE | Northing: 6705632 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 183 | Observer: ST

Zone: 51 | Easting: 311177 mE | Northing: 6705366 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Eucalypt woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 184 | Observer: ST

Zone: 51 | Easting: 311374 mE | Northing: 6705482 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 185 | Observer: ST

Zone: 51 | Easting: 311359 mE | Northing: 6705713 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 186 | Observer: ST

Zone: 51 | Easting: 311399 mE | Northing: 6706063 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 187 | Observer: ST

Zone: 51 | Easting: 311550 mE | Northing: 6706060 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 188 | Observer: ST

Zone: 51 | Easting: 311524 mE | Northing: 6705753 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 189 | Observer: ST

Zone: 51 | Easting: 311764 mE | Northing: 6705614 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 190 | Observer: ST

Zone: 51 | Easting: 311730 mE | Northing: 6705907 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 191 | Observer: ST

Zone: 51 | Easting: 311950 mE | Northing: 6706211 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 192 | Observer: ST

Zone: 51 | Easting: 311973 mE | Northing: 6705931 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 193 | Observer: ST

Zone: 51 | Easting: 312009 mE | Northing: 6705704 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 194 | Observer: ST

Zone: 51 | Easting: 312175 mE | Northing: 6705813 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 195 | Observer: ST

Zone: 51 | Easting: 312306 mE | Northing: 6705864 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 196 | Observer: ST

Zone: 51 | Easting: 312156 mE | Northing: 6706195 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 197 | Observer: ST

Zone: 51 | Easting: 311997 mE | Northing: 6706376 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021

Habitat Assessment #: 198

Observer: ST

Zone: 51

Easting: 311986 mE

Northing: 6706686 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 199 | Observer: ST

Zone: 51 | Easting: 311836 mE | Northing: 6706866 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 200 | Observer: ST

Zone: 51 | Easting: 311889 mE | Northing: 6707150 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021

Habitat Assessment #: 201

Observer: ST

Zone: 51

Easting: 311617 mE

Northing: 6707071 mN

Fire History: >5 years


Landform: Flat plain

Soil Type: Clay

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 202 | Observer: ST

Zone: 51 | Easting: 311458 mE | Northing: 6707204 mN

Fire History: >5 years | Landform: Waste dump | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 203 | Observer: ST

Zone: 51 | Easting: 311287 mE | Northing: 6707129 mN

Fire History: >5 years | Landform: Waste dump | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021

Habitat Assessment #: 204

Observer: ST

Zone: 51

Easting: 311198 mE

Northing: 6707424 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021

Habitat Assessment #: 205

Observer: ST

Zone: 51

Easting: 311288 mE

Northing: 6707827 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 206 | Observer: ST

Zone: 51 | Easting: 311227 mE | Northing: 6708166 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 207 | Observer: ST

Zone: 51 | Easting: 311225 mE | Northing: 6708503 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 208 | Observer: ST

Zone: 51 | Easting: 311191 mE | Northing: 6708819 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 209 | Observer: ST

Zone: 51 | Easting: 311191 mE | Northing: 6708970 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 210 | Observer: ST

Zone: 51 | Easting: 311383 mE | Northing: 6708405 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 211 | Observer: ST

Zone: 51 | Easting: 309624 mE | Northing: 6712455 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 212 | Observer: ST

Zone: 51 | Easting: 309652 mE | Northing: 6712140 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 213 | Observer: ST

Zone: 51 | Easting: 309659 mE | Northing: 6711838 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 214 | Observer: ST

Zone: 51 | Easting: 309708 mE | Northing: 6711521 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 215 | Observer: ST

Zone: 51 | Easting: 309689 mE | Northing: 6711211 mN

Fire History: >5 years | Landform: Creekline | Soil Type: Rock

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 216 | Observer: ST

Zone: 51 | Easting: 309749 mE | Northing: 6710892 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 217 | Observer: ST

Zone: 51 | Easting: 309723 mE | Northing: 6710561 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 218 | Observer: ST

Zone: 51 | Easting: 309770 mE | Northing: 6710250 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 219 | Observer: ST

Zone: 51 | Easting: 309909 mE | Northing: 6710431 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 220 | Observer: ST

Zone: 51 | Easting: 309882 mE | Northing: 6710739 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 221 | Observer: ST

Zone: 51 | Easting: 309860 mE | Northing: 6711045 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 222 | Observer: ST

Zone: 51 | Easting: 309849 mE | Northing: 6711380 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 223 | Observer: ST

Zone: 51 | Easting: 309841 mE | Northing: 6711699 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Casuarina woodland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 224 | Observer: ST

Zone: 51 | Easting: 309787 mE | Northing: 6712006 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 225 | Observer: ST

Zone: 51 | Easting: 309798 mE | Northing: 6712292 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 226 | Observer: ST

Zone: 51 | Easting: 310030 mE | Northing: 6711958 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 227 | Observer: ST

Zone: 51 | Easting: 310045 mE | Northing: 6711605 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 228 | Observer: ST

Zone: 51 | Easting: 310100 mE | Northing: 6711302 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 229 | Observer: ST

Zone: 51 | Easting: 310116 mE | Northing: 6710984 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 230 | Observer: ST

Zone: 51 | Easting: 310135 mE | Northing: 6710619 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 231 | Observer: ST

Zone: 51 | Easting: 310218 mE | Northing: 6710339 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 232 | Observer: ST

Zone: 51 | Easting: 310324 mE | Northing: 6710524 mN

Fire History: >5 years | Landform: Gentle slope | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 233 | Observer: ST

Zone: 51 | Easting: 310275 mE | Northing: 6710910 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 234 | Observer: ST

Zone: 51 | Easting: 310277 mE | Northing: 6711265 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 235 | Observer: ST

Zone: 51 | Easting: 310261 mE | Northing: 6711553 mN

Fire History: >5 years | Landform: Gentle slope | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 236 | Observer: ST

Zone: 51 | Easting: 310414 mE | Northing: 6711147 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 237 | Observer: ST

Zone: 51 | Easting: 310500 mE | Northing: 6710876 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 238 | Observer: ST

Zone: 51 | Easting: 310507 mE | Northing: 6710536 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021

Habitat Assessment #: 239

Observer: ST

Zone: 51

Easting: 309474 mE

Northing: 6711015 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 240 | Observer: ST

Zone: 51 | Easting: 309488 mE | Northing: 6711312 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 241 | Observer: ST

Zone: 51 | Easting: 309439 mE | Northing: 6711621 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 242 | Observer: ST

Zone: 51 | Easting: 309410 mE | Northing: 6712007 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 243 | Observer: ST

Zone: 51 | Easting: 309212 mE | Northing: 6712174 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 244 | Observer: ST

Zone: 51 | Easting: 309212 mE | Northing: 6712174 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 245 | Observer: ST

Zone: 51 | Easting: 309263 mE | Northing: 6711822 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 246 | Observer: ST

Zone: 51 | Easting: 309306 mE | Northing: 6711471 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 247 | Observer: ST

Zone: 51 | Easting: 309024 mE | Northing: 6711771 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Completely degraded



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021

Habitat Assessment #: 248

Observer: ST

Zone: 51

Easting: 308955 mE

Northing: 6712090 mN

Fire History: >5 years


Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS


Date: 16/11/2021 | Habitat Assessment #: 249 | Observer: ST

Zone: 51 | Easting: 308829 mE | Northing: 6712056 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 250 | Observer: ST

Zone: 51 | Easting: 308006 mE | Northing: 6712820 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 251 | Observer: ST

Zone: 51 | Easting: 308195 mE | Northing: 6712925 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 252 | Observer: ST

Zone: 51 | Easting: 308365 mE | Northing: 6712960 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Very good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 253 | Observer: ST

Zone: 51 | Easting: 308359 mE | Northing: 6713180 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 254 | Observer: ST

Zone: 51 | Easting: 308563 mE | Northing: 6713218 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 255 | Observer: ST

Zone: 51 | Easting: 308778 mE | Northing: 6713229 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 256 | Observer: ST

Zone: 51 | Easting: 308962 mE | Northing: 6713107 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Open shrubland | Surface: Clay with pebbles

Habitat Quality: Good



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 257 | Observer: ST

Zone: 51 | Easting: 309158 mE | Northing: 6712929 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Clay

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 258 | Observer: ST

Zone: 51 | Easting: 309314 mE | Northing: 6712674 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021

Habitat Assessment #: 259

Observer: ST

Zone: 51

Easting: 309058 mE

Northing: 6712656 mN

Fire History: >5 years

Landform: Flat plain

Soil Type: Sand with pebbles

Habitat Structure: Disturbed

Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 260 | Observer: ST

Zone: 51 | Easting: 308912 mE | Northing: 6712569 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 261 | Observer: ST

Zone: 51 | Easting: 308691 mE | Northing: 6712603 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Disturbed | Surface: Clay with pebbles

Habitat Quality: Completely degraded





TERRESTRIAL ECOSYSTEMS

Date: 16/11/2021 | Habitat Assessment #: 262 | Observer: ST

Zone: 51 | Easting: 308871 mE | Northing: 6712843 mN

Fire History: >5 years | Landform: Flat plain | Soil Type: Sand with pebbles

Habitat Structure: Bushy shrubland | Surface: Clay with pebbles

Habitat Quality: Disturbed



TERRESTRIAL ECOSYSTEMS


DETECTION DOG