

Photo 1 Removal tree facing north



Photo 2 Removal tree facing south



Photo 3 Termites at removal tree base



Photo 4 Removal tree leaning at base