1. Looking south over Toodyay Road in line with proposed works.



2. Looking right from previous photo showing pole that will be replaced.



3. On Toodyay Road looking south to area of proposed works



4. On the road to the carpark looking up towards Toodyay Road, at the area of proposed works



5. Close up of the area in photo 4



6. Opposite view from previous photo looking towards car park and picnic area. Tree to the left of the stairs to be removed



7. Vegetation in the area between Toodyay Road and the road to the car park. This is the area where most of the clearing is proposed. There are a few native trees, *Allocasuarina huegeliana*, young *Eucalyptus wandoo* and *Corymbia calophylla*. The majority of the vegetation area native species, *Calothamnus* spp, *Callistemon phoeniceus* and *Hakea petiolaris*. The understorey is predominately introduced veldt grass, *Ehrharta calycina*.

